



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78048
Promised Date: 24 OCT 25



Customer #: 11706
SHAW, PAULA



CUSTOMER WORK ORDER

WO #: 78048 (Appointment Date: 15 OCT 2025 - Time: 02:00pm)

Customer: 11706 - SHAW, PAULA - (812) Stock #: 11211

661-2296

Tag:

Author: GA

Location: 1113 CHECK STATUS WITH

SR

Stock Desc: 2022 5W KEYSTONE

MONTANA 3791RD

Chassis #: 4YDFM0T24N4703710

Serial #: 4YDFM0T24N4703710

Mileage:

Licence:

Invoice #: 424346

Date In: 15 OCT 25

Promised: 31 OCT 25

Date Sched:

Completed: 12 NOV 25

Warr. Date: 25 JUN 22

Job #1 - External

COMPLAINT: NOT GETTING POWER WHEN PLUGGED IN TO SHORE POWER. GETS POWER WHEN USEING TO GENERATOR, CUSTOMER HEARD POP AND LOST POWER AND WILL NOT COME BACK ON

CAUSE: Found no problem or damage to the electric transfer switch or breakers.

CORRECTION: Unscrewed the cover to the transfer switch and plugged in the shore power. The transfer switch to the shore power side tripped on, next went to the in-command, and turned on the front and rear AC to inspect the transfer switch for problems. Checked the voltage at the transfer switch while on shore and had 119 volts. Unplugged the shore power and started the generator after the generator tripped on the transfer switch, and checked the volts. Got 125 volts from the generator. Shut off the generator and plugged the shore power back in and watched the transfer switch trip on.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: BOTH REAR SLIDE ROOMS RUN IN AND OUT CROOKED

CAUSE: Schwintek Motors had a bad Halifax sensor causing them not to communicate properly.

CORRECTION: Ran out all 5 sliderooms but did notice the sliderooms in the living area were going out and in crooked. Got the shop testing control box for the Schwintek sliderooms, checked the doorside and then the off doorside. There was no difference between the sliderooms. Unscrewed the original Schwintek motors and put in the test slideroom motors and test the doorside and the off doorside. Synchronized both sliderooms then fully ran them out and in with no hesitation. Put in PO 4 new Schwintek motors. Unscrewed the Schwintek motors and put in new motors then tested after synchronizing the sliderooms.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



236575	IN-WALL MOTOR - LIPPERT	2.00	N/C	N/C
236575	IN-WALL MOTOR - LIPPERT	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - External

CHECK EXTENDED WARRANTY

Subtotal for Job #3: 0.00

Job #24-452 - Warranty

COMPLAINT: RECALL FOR STOVE

The remedy is to disconnect the 12-volt power to the stove lights, cap incoming wires. Please see attached Safety Advisory.

CAUSE: Perform recall

CORRECTION: Went to the stove and pulled off the burner grate then took pictures of the process of the recall service. Cut the wire to the lights in the stove then capped the wires. Put the stove top back together.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	90.00

Subtotal for Job #24-452: 90.00

Parts Total:	0.00
Labour Total:	90.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 90.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 12 Nov 2025

Customer Signature : _____

W/O: 78048
Promised Date: 31 OCT 25



Customer #: 11706
SHAW, PAULA

