



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78057
Promised Date:
24 OCT 25

CUSTOMER WORK ORDER

WO #: 78057 (Appointment Date: 16 OCT 2025 - Time: 01:00pm)

Customer: 27089 - DUKE, ALLEN -
270-570-4799

Tag:

Author: GA

Location: 1103 BH TO CLOSE

Stock #: 11579

Stock Desc: (11579) 2025 COACHMEN
CATALINA SUMMIT SERIES 261BHS

Chassis #: 5ZT2CARB1SU045761

Serial #: 5ZT2CARB1SU045761

Mileage:

Licence:

Invoice #:

Date In: 16 OCT 25

Promised: 31 OCT 25

Date Sched:

Completed: 30 OCT 25

Warr. Date: 12 APR 25



Job #1 - Internal

COMPLAINT: WE HAVE ALREADY FIXED THIS ONCE THE WALL ON THE SLIDE SHOULD BE GLUED DOWN AND NEEDS TO BE FIXED CUSTOMER WILL SHOW. MARKED WITH BLUE TAPE

CAUSE: Staples popped thru panel.

CORRECTION: Removed seam tape and blind rope. Moved out the dinnette cushion and board to cut seam tap3 low. Removed staples blocking pan3l from sittin flush. Adjusted air regulator to staple gun and secured panel back to wall properly. Install new seam tape. Reinstalled blind tansion rope and put dinnette back together.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|------|---------------|------|-------|-------|
| SS | SHOP SUPPLIES | 1.00 | N/C | N/C |

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: LIGHT STRIPS ON FRONT OF CAMPER ARE COMING OUT OF THEIR TRACK ON BOTH SIDES

CAUSE: Lights pulled from track.

CORRECTION: Doorside Accent Light was bubbled out in multiple spots. Attempted to put it back in track but its length it to long so i had to remove from track at the lowest bubbled spot and work light into track upward till excess reached the top end and cut about a half an inch off and sealed the end over with dicor. Light on the OffDoorSide was just out of track on on one side of light so i worked it back into the track.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 37.00 |

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: FABRIC ON VINYL FLOOR IN SLIDE ROOM IS COMING LOOSE

CAUSE: Slide material under lip of slideroom vynle came loose.

CORRECTION: Cut some cardboard the length of slideroom and slide it u der the lip of Vynle slideroom floor and then pulled the slide material out as much as possible and sprayed the backside with 3M Adhesive

Customer #: 27089
DUKE, ALLEN



and glued slide carpet back to the bottom sid3 of Vynle floor and stretched back into place.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 55.50 |

Subtotal for Job #3: 55.50

Job #WINTER - External

Transferred to BAS*78222 on 31 OCT 25

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

| Code | Description | Mechanic | Total |
|------|----------------|----------|-------|
| Z990 | WINTERIZE UNIT | CCV | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|------|---------------|------|-------|-------|
| SS | SHOP SUPPLIES | 0.00 | N/C | N/C |

Subtotal for Job #WINTER: 0.00

Customer Order Work

| | |
|--------------------------|--------------|
| Parts Total: | 0.00 |
| Labour Total: | 92.50 |
| Sublet Total: | 0.00 |
| Extras Total: | 0.00 |
| WORK ORDER TOTAL: | 92.50 |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Nov 2025

W/O: 78057
Promised Date: 31 OCT 25



Customer #: 27089
DUKE, ALLEN

