



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78067
Promised Date:
24 OCT 25

CUSTOMER WORK ORDER

WO #: 78067 (Appointment Date: 17 OCT 2025 - Time: 01:30pm)

Customer: 55891 - BRENNING, JODY -
270-748-8585

Tag:

Author: BJW

Location: 1124 BJ TO MEASURE FOR
COVER WITH CAM

Stock #: 11474

Stock Desc: 2025 TT FOREST RIVER

CHEROKEE GREY WOLF 23MK

Chassis #: 4X4TCKY21SK092209

Serial #: 4X4TCKY21SK092209

Mileage: 0

Licence:

Invoice #: 424688

Date In: 17 OCT 25

Promised: 31 OCT 25

Date Sched:

Completed: 24 NOV 25

Warr. Date: 13 JUN 25

Job #1 - Warranty

COMPLAINT: CHECK THE A/C GOT A E3 CODE CUSTOMER STATES THERE IS A LOUD NOISE WHEN TURNING OFF AND IT DOES NOT SOUND NORMAL. CUSTOMER ADVISES THAT THERE IS BLACK STUFF COMING FROM THE VENTS. TECH WILL HAVE TO LET IT RUN FOR A WHILE BEFORE IT WILL DUPLICATE.

CAUSE: Blower fan had come loose and moved along the shaft. It was against the black styrofoam inside the discharge vent. The 120 volt wiring was installed thru the wrong hole. The clamp to hold the wiring is on the top side of the control box. They ran the wiring in the heat strip socket hole. Some of the WAGO connectors feel loose.

CORRECTION: I removed the inside air conditioner plenum. I found that the fan had moved on the motor shaft. I adjusted the fan and tightened down the set screw. I removed all of the WAGO connectors and replaced them with crimp connectors. I removed the 120 volt wiring from the control box and installed it into the correct hole. I tested the air conditioner and put the plenum back together. I let the air conditioner run over the weekend and it is all working as it should.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	185.00

Subtotal for Job #1: 185.00

Job #2 - Warranty

COMPLAINT: awning not folding in correctly. IT IS NOT CLOSING ALL THE WAY CHECK AND ADVISE.

CAUSE: Morning material is rolled up with rankles.

CORRECTION: I rolled out the awning and found that the canvas had shrank in the center. The canvas needs replaced.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	185.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 55891
BRENNING, JODY

10575 15' SOLID BLACK UNIVERSAL FABRIC 1.00 251.93 251.93
- S

Subtotal for Job #2: 529.43

Job #3 - Warranty

COMPLAINT: toilet not working right WHEN CUSTOMER SITS ON IT IT SHAKES. CUSTOMER ADVISES THAT IT DOES NOT FEEL STURDY. SEE BJ IF YOU HAVE QUESTIONS ON THIS

CAUSE: Toilet feels loose.

CORRECTION: I checked the toilet and it is loose. I removed the toilet to check the flange. I did not find anything wrong with the flange. I checked all 4 screws to be sure that they are tight. I put the toilet back in place and tightened the anchor bolts. The toilet feels a bit tighter. To the floor after I reinstalled it.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	55.50

Subtotal for Job #3: 55.50

Job #4 - Warranty

COMPLAINT: blinds needs to be lowered. CUSTOMER SAYS THE CURTAINS NEEDS TO BE LOWERED SO YOU CAN CLOSE THE BLINDS ALL THE WAY THIS IS THE BIG WINDOW BY THE DINNETTE AND THE BIG WINDOW BY THE COUCH. SEE BJ, HE CAN EXPLAIN THIS BETTER.

CAUSE: The certain hold back brackets on all of the living room windows had been mounted too close together.

CORRECTION: I had to remove and move both certain hold back brackets on the small rear windows. The blinds would not pass between them. The slide room window only had one bracket that had to be moved. The back wall window blind was not mounted in the center of the window. I unhooked the blind and shifted it over so that it was center. Now, all of the blinds pass the certain hold backs.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	55.50

Subtotal for Job #4: 55.50

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit and drain tanks

CORRECTION: I winterized the unit and drained the tanks. I used 2 gallons of antifreeze.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

W/O: 78067
Promised Date: 31 OCT 25



Customer #: 55891
BRENNING, JODY





Job #ROOFT - Internal

COMPLAINT: INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF SEALANT INCLUDED.

CAUSE: Check roof and seal voids and gaps

CORRECTION: I checked the roof and sealed as needed.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		GAH	N/C

Parts				
Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #7 - Internal

THE WINTER AND ROOFT AND A COVER IS FREE GET WITH BRIAN CUSTOMER DOES NOT HAVE A COVER

Subtotal for Job #7: 0.00

Job #8 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE TWO TV'S INSTALLED IN TRAILER. CUSTOMER WILL BRING TV'S BUT WILL NEED TO PURCHASE BRACKETS. SEE BJ ABOUT BRACKETS AND LOCATION. CUSTOMER SHOWED BJ WHERE SHE WANTS THE TV'S AND WHAT TYPE OF BRACKETS SHE WANTS.

CAUSE: The customer wants 2 TVs mounted with new wall mounts.

CORRECTION: I was able to use the customer supplied wall mount in the living room. I installed an offset TV mount in the bedroom. This had to be done dew to the TV mounting location in the wall. I hooked up the new TV and tested it. Everything is working as it should.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		GAH	N/C

Parts				
Part #	Description	Qty	Price	Total
380317	Bracket - TV Swing Arm - Single - 9" - w/Nylon Quick Disconnect - Black - Replaces KRV 339878	1.00	N/C	N/C

Subtotal for Job #8: 0.00

Job #9 - Internal

COMPLAINT: CUSTOMER ADVISES THAT ONE OF THE PLUGS IN THE BEDROOM IS LOOSE. SEE BJ FOR EXACT LOCATION. THIS IS THE INVERTED 110V OUTLET THAT IS MOUNTED TO THE DOOR SIDE INTERIOR WALL IN THE MASTER BEDROOM

CAUSE: Screw fell out of lower inverter mount.

CORRECTION: I reinstalled the screw

Labor				
-------	--	--	--	--



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Subtotal for Job #9:			0.00

Job #10 - Warranty

COMPLAINT: THE BULB SEAL IS PEELING OFF OF THE WALL OVER THE SLIDE ROOM

CAUSE: Bulb seal got stuck to slidering trim. The bulb seal was pulled off. It has been rolled up inside the top of the slide room. It needs replaced.

CORRECTION: I removed the old bulb seal. I cleaned up the sealer that was all over the slide room trim. I installed a new bulb seal and cap sealed the bulb seal.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	92.50

Parts				
Part #	Description	Qty	Price	Total
13-1095A	SLIDE ON "D" SEAL X FT.	8.00	2.48	19.84

Subtotal for Job #10: 112.34

Parts Total:	271.77
Labour Total:	666.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 937.77

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 24 Nov 2025

Customer Signature : _____

W/O: 78067
Promised Date: 31 OCT 25



Customer #: 55891
BRENNING, JODY

