

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2482511
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAMB8SU044310
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT231MKS-8
MICHAEL E BREITWEISER		DEALER RO #	78104
13199 N COUNTY ROAD 175 E		CLAIM START DATE	10/28/2025
Chrisney, IN 47611		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	10/07/2025	WARRANTY EXPIRATION DATE	10/07/2026

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 10-9-01-00-000158 Stabilizer Jack - Bolt On, each - Frame & Chassis/Levelers, Underbelly/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:45:25 :: CUSTOMER ADVISES THAT THE ALL TREAD IS BENT ON BOTH REAR STABILIZER JACKS. Rear stabilizer jack bent Inspection of the rear stab jacks found that the screw rod is bent that moves the jack up and down. Put a parts request in for two new jacks

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$74.00
Serial#	Appr Hrs	0.40	Appr Labor Amt \$74.00

Notes
 AUTHORIZED AS REQUESTED

Labor

Line# 2 **Operation Code** **Operational Description**
 20-49-19-00-000588 Front Moldings, each - Exterior/Front, Fiberglass Cap, Cab Over/Reseal/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:46:19 :: CUSTOMER ADVISES THAT THERE ARE SOME VOIDS IN SILICONE ON ONE SIDE OF THE SLIDE AND AROUND SOME OF WINDOWS. AND THE REAR TOP Voids in sealer Touched up the spots pointed out with clear silicone. And checked over the camper. All good now

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 20-43-01-00-000589 Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:47:17 :: CUSTOMER ADVISES THAT EITHER THE DECAL OR THE PAINT TO THE LEFT OF THE STORAGE COMPARTMENT ON THE OFF DOOR IS PEELING. Decal torn and air bubble After inspection of the decal seen that it is tore in two spots. Put in a parts request

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$74.00
Serial#	Appr Hrs	0.40	Appr Labor Amt \$74.00

Notes
 AUTHORIZED AS REQUESTED

Labor

Line# 4 **Operation Code** **Operational Description**
 30-101-01-00-001073 Hinged Passage Door Hinge, each - Interior/Interior Doors/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:48:06 :: WHEN TRAVELING THE BATHROOM DOOR OPENS THIS IS THE INSIDE DOOR NOT THE OUTSIDE DOOR Bathdoor open during transport Put shims behind hinges to move door latch more in the striker. So it dont flex and come out

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50

Notes

AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$240.50	Approved	Labor Amt	\$240.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$240.50		Total	\$240.50

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.