

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2482533
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAZB9TX036189
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT343BHTSLE
CHRISTOPHER A FOSTER		DEALER RO #	78112
4608 SWEETSER AVE		CLAIM START DATE	10/28/2025
Evansville, IN 47714		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	10/21/2025	WARRANTY EXPIRATION DATE	10/21/2026

Claim Line Details

Line#	Operation Code	Operational Description	
Line# 1	30-102-24-00-001094	Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:56:32 :: OUTDOOR KITCHEN CEILING IS SAGGING DOWN Outdoor ceiling was not secure After inspection of the outside kitchen are i found that the ceiling wasn't secure in the front. So i shot some stapels along the front and filled with putty. Good to go now		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
	Notes		
Line# 2	30-101-24-00-001079	Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:58:12 :: CLOSET IN MASTER BEDRRM HAS COME OUT OF IT'S TRACKS Closet track guide out of track Upon exterior inspection found that clost door was not moving properly. Found that on of the plastic guides was out of the track so i put it back in and door works properly		
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$55.50
	Notes		
Line# 3	20-66-19-00-000665	Entry Door Window - Exterior/Entry Doors/Reseal/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:58:53 :: 2 WINDOW SEALS WERE TUCKED IN CAUSING VOID AROUND WINDOW Window seal had a void in it On my inspection of the exterior i found the the window seal wasn't installed correctly. So i got the seal installed correctly and is good to go now		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
	Notes		
Line# 4	40-196-01-11-001306	LED Light - Electrical/12 Volt Interior/Replace/Electrical	

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-10-28 16:59:23 :: LIGHT OVER THE KITCHEN COUNTER ISN'T WORKING Light don't work Took light off and it flickerd but won't stay on. So i replaced it and it works properly now

Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$37.00

Serial# Appr Hrs 0.20 Appr Labor Amt \$37.00

Notes

Labor

Line# 5

Operation Code

20-46-01-00-000721

Operational Description

Window - Exterior/Windows/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-10-28 17:00:52 :: SCRATCH ON THE OUTSIDE OF NUBER 3 SLIDE WINDOW FRAME Scratch on 3rd slideroom bottom window Inspection of exterior found a scratch on 2 spots on the window frame. Put in a parst request for a new window.

Model# Dlr Sub Hrs 0.60 Sub Labor Amt \$111.00

Serial# Appr Hrs 0.60 Appr Labor Amt \$111.00

Notes

OP CODE CJHANGE

REQUIRES PHOTOS- CAN IT BE SANDED AND PAINTED?

these are scratches on the frame of a window ??

AUTHORIZED AS REQUESTED

Labor

Line# 6

Operation Code

20-58-01-00-000813

Operational Description

Lower Radius Metal, per piece - Exterior/Metal, Aluminum Siding/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-10-28 17:01:52 :: ON THE METAL BEHIND NUMER 1 SLIDE ON THE OFF DOOR SIDE Dent in exterior metal Found dent in metal on exterior inspection. Put in a parts request

Model# Dlr Sub Hrs 4.00 Sub Labor Amt \$740.00

Serial# Appr Hrs 4.00 Appr Labor Amt \$740.00

Notes

REQUIRES PHOTOS-

photos added

AUTHORIZED AS REQUESTED

PLEASE UPDATE PER EMAIL REQUEST

updated time thank you

AUTHORIZED AS REQUESTED

Labor

Line# 7

Operation Code

60-668-01-00-001480

Operational Description

City Water Connection - Plumbing/Nautilus Water Mgmt System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-10-28 17:02:31 :: CITY WATER INLET IS LEAKING City fill port leaking when the water pump was on Inspection of the cty port it was dripping a little when pressurized. Tried to see if debris was making it do that but i ended up changing it for a new one. Took leaky one off put budle tape on new one and tightened the water line then installed it and then sealed the outside with silicone and tested it no leaks. Good to go

Model# Dlr Sub Hrs 0.30 Sub Labor Amt \$55.50

Serial# Appr Hrs 0.30 Appr Labor Amt \$55.50

Notes

Submitted			Approved		
Labor Amt	\$1,073.00		Labor Amt	\$1,073.00	
Parts & Freight	\$0.00		Parts & Freight	\$0.00	
Total	\$1,073.00		Total	\$1,073.00	

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.