

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78118
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 32316 - KEVIN KAISER
Address: 501 SECTION ST NEWBURGH, IN

47630

Phone: 812-453-1043

Stock Number: 11647 - 2026 DELTA 262RB 7M5TD292XTC307174

VIN: 7M5TD292XTC307174 HIN: SER#: 7M5TD292XTC307174

Mileage: 0 Work Order Comp: 30 NOV 25

Auth. No: Dealer #:

Warr. Date: 15 AUG 25 Work Order Date: 22 OCT 25 Inv #: 424993

WO # Job # Description JOB INFORMATION

78118 1 THE WALL BETWEEN THE DINETTE AND THE THEATER SEATS CAME APART
AGAIN
Turned in request for parts
REMOVED THE RECLINERS AND TOOK APART THE DINETTE BOOTH I
MEASURE AND CUT OUTTHE LOWER BOARD AND DRILLED HOLES INTHE NEW
BOARD FOR THE WIRES AND AND DRILLED HOLES FOR THE NEW SCREWS
AND RESCESSED THE MOUNTING HOLES . I THEN INSTALLED AND MADE
SURE THE SCREWS DID NOT GO THROUGH THE FLOOR. I THEN MEASURED
FOR THE CROSS BRACES AND DRILLED POCKET HOLES FOR THE SCREWS
AND INSTALLED WITH LIQUID NAILS AND SCREWS I CUT AND IINSTALLED
3 BRACES I ALSO INSTALLED METAL L BRACKETS TO HELP HOLLD
TOGETHER. THEN I INSTALLED THE DECORE END PEICE AND INSTALLED
SCREWS I LIQUID NAILED IT ALSO AND INSTALLED EXTRA SCREWS . I
HAD TO TAKE THE SEAT APART AND THE WIRNG TO GET THE NEW PANEL
INSTALLED ON THE INSIDE OF THE BOOTH ONSCE INSTALLED I THEN
REINSTALLED THE WIRING I INSTALLED NEW PANELING AND NEW TRIM
AROUND THE PANELING AND FLLD ALL THE HOLES WITH PUTTY AND
REINSTALLED THE RECLINERS AND AD RAN ROOM IN AND OUT SEVERAL
TIMES TO MAKE SUR EVERYTHING HELD PUTTY AND THEN
REINSTALLED THE RECLINERS.

78118 2 WHEN THE BLACK TANK FLUSH IS BEING USED IT LEAKS WATER AND SOME
WATER HAS GONE TO THE UNDER BELLY
traced down under the unit in the underbelly the leak i then
noticed it was coming from above the tank i then found under the
sink the check vlave had bugs init and was leaking badly i

Claim : 78118

 WO # Job # Description JOB INFORMATION

cleaned out the bugs and put a screen over the top of the vlave
 and then i had to cove r the access holes in the underbelly and
 sealed them with silicone.

78118 5 REAR LEFT STABILIZER IS BENT
 Turned in request for parts

78118 4 UNDERBELLY WAS FILLED WITH WATER WHEN CUSTOMER DROVE AWAY FROM
 THERE LOCATION THE CAMPER HAD BEEN FOR OVER A WEEK. INSPECT
 WHERE WATER MAY HAVE ENTERED THE UNDERBELLY AND VERIFY UNDERBELLY
 IS OK
 opened the underbelly in several placed to inspect and did not
 see any damage from water . i put wood on top of opening s and
 screwed the underbelly to it and sealed with silicone.

 Part No Job# Description PARTS Qty Price Total

 27473 1 Stile - 2.5 x 108 - LC Square - H 1.00 8.92 8.92
 27479 1 27479 Panel - DİÇÜcor - 4 Star - 1.00 31.72 31.72
 27484 1 Trim - Batten - Beveled x2 - 3.6 2.00 1.91 3.82
 27493 1 27493 Trim - J-Moulding - 0.225 x 0.00 4.65 0.00
 28527 1 TRIM - J-MOLDING -5/32 - ALLIANCE 16.00 0.17 2.72
 12345 1 2X4X8 LUMBER 3.00 4.47 13.41
 219088 2 SILICONE II BLACK 1.00 13.56 13.56
 04-7077 5 Leveling Jack; LoPro Series SJ24 1.00 59.76 59.76

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 25.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 25.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 2.00 185.00 370.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 4.00 185.00 740.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.75 185.00 138.75
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.09 185.00 16.65
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.33 185.00 61.05
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.08 185.00 14.80
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.00 185.00 185.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS FREIGHT 1.00 95.55 95.55

Parts Total: 133.91
 Labour Total: 1,526.25
 Sublet Total: 0.00
 Extras Total: 95.55

>>>>> Claim Total: 1,755.71

Customer Signature: _____

Date: _____

Claim : 78118

```
*****
Excode   Job#  Description      EXTRAS              Qty    Price    Total
*****
```