

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 2499547
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CANB6SN301263
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 300 / 300
ITEM # CAT243RBSLE-300
DEALER RO # 78127
CLAIM START DATE 11/13/2025
CLAIM END DATE 01/01/1900

Labor rate: \$185.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line#	Operation Code	Operational Description		
1	RC-720-09-00-004710	25V264, 2025-217 - INCORRECT OVER CURRENT PROTECTION - INSPECTION AND REMEDY - Recall/Wiring/Perform/No Tread Code		
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-11-13 13:59:37 :: 25V264, 2025-217 - INCORRECT OVER CURRENT PROTECTION The front exterior accent lamp wire (16AWG) may be on a 30AMP breaker, whereas it should be on a 10AMP over current device. The awning may be missing the required 15AMP over current protection. The auto-leveling system may be wired to constant hot on a 30AMP mini-breaker. 3 recalls 2 mini breakers tied together with copper buss bar is in underbelly so self leveling is correct. Awning needed the 15A inline fuse installed which i did at distribution panel. Accent lights in front needed a 10A fuse installed which i did at the switch in the compartment.				
Model#	Dlr Sub Hrs	0.75	Sub Labor Amt	\$138.75
Serial#	Appr Hrs	0.75	Appr Labor Amt	\$138.75
Notes AUTHORIZED AS REQUESTED				

Submitted	Labor Amt	\$138.75
	Parts & Freight	\$0.00
	Total	\$138.75

Approved	Labor Amt	\$138.75
	Parts & Freight	\$0.00
	Total	\$138.75

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.