

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<table style="width: 100%;"> <tr> <td style="width: 50%;">CLAIM STATUS</td> <td>Authorized</td> </tr> <tr> <td>CLAIM</td> <td>2483640</td> </tr> <tr> <td>CLAIM ORIGIN</td> <td>WEB</td> </tr> <tr> <td>ORIGINAL CLAIM ID</td> <td></td> </tr> <tr> <td>VIN</td> <td>5ZT2CATB8SX032741</td> </tr> <tr> <td>CHASSIS VIN</td> <td></td> </tr> <tr> <td>MILEAGE</td> <td>0</td> </tr> <tr> <td>SITE/WAREHOUSE</td> <td>205 / 205</td> </tr> <tr> <td>ITEM #</td> <td>ACAT283RKSLE</td> </tr> <tr> <td>DEALER RO #</td> <td>78142</td> </tr> <tr> <td>CLAIM START DATE</td> <td>10/29/2025</td> </tr> <tr> <td>CLAIM END DATE</td> <td>01/01/1900</td> </tr> </table>	CLAIM STATUS	Authorized	CLAIM	2483640	CLAIM ORIGIN	WEB	ORIGINAL CLAIM ID		VIN	5ZT2CATB8SX032741	CHASSIS VIN		MILEAGE	0	SITE/WAREHOUSE	205 / 205	ITEM #	ACAT283RKSLE	DEALER RO #	78142	CLAIM START DATE	10/29/2025	CLAIM END DATE	01/01/1900
CLAIM STATUS	Authorized																								
CLAIM	2483640																								
CLAIM ORIGIN	WEB																								
ORIGINAL CLAIM ID																									
VIN	5ZT2CATB8SX032741																								
CHASSIS VIN																									
MILEAGE	0																								
SITE/WAREHOUSE	205 / 205																								
ITEM #	ACAT283RKSLE																								
DEALER RO #	78142																								
CLAIM START DATE	10/29/2025																								
CLAIM END DATE	01/01/1900																								
Labor rate: \$185.00 OWNER INFORMATION BOBBY LYNN GOURLEY 1335 SCHILLINGER RD Evansville, IN 47725 USA																									
Retail Date of Purchase 10/15/2024	WARRANTY EXPIRATION DATE 10/15/2025																								

Claim Line Details

Labor

Line# 1	Operation Code 30-103-24-00-001125 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-10-29 14:06:13 :: LOOK AND FLOOR THAT IS COMING LOOSE Some appears to have rolled under room when it ran in. Glued edges and sealed floor	Operational Description Linoleum - Interior/Flooring/Repair/No Tread Code
Model#	Dlr Sub Hrs 0.50	Sub Labor Amt \$92.50
Serial#	Appr Hrs 0.50	Appr Labor Amt \$92.50
Notes AUTHORIZED AS REQUESTED		

Labor

Line# 2	Operation Code 10-13-02-00-000211 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-10-29 14:07:54 :: CUSTOMER ADVISES THAT THE SLIDE ROOM IS CROOKED WHEN IT IS OUT. SEE SERVICE HISTORY. Noticed to top was out farther than the bottom. And not sealed on inside when out Checked on lower side and found the ram was already to furthest position on the frame and the adjustment nuts was already at the end of adjustment . We found the threaded end of the ram could be adjusted out. So i pulled the set screw and ran the thread out and reinstalled the set nut the reconnected ran to room and adjusted the bell stop . Ran room. In and out. And now room seals at the bottom.	Operational Description Slide Out Room - Frame & Chassis/Slide Out System/Adjust/No Tread Code
Model#	Dlr Sub Hrs 1.50	Sub Labor Amt \$277.50
Serial#	Appr Hrs 1.50	Appr Labor Amt \$277.50
Notes AUTHORIZED AS REQUESTED		

Labor

Line# 3	Operation Code 30-100-01-00-001056 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-10-29 14:08:26 :: LOOK AT THE BACK SPLASH IT IS COMING LOOSE Turned in request for parts NEED TO REMOVE AND REPLACE	Operational Description Backsplash - Interior/Cabinetry/Replace/No Tread Code
Model#	Dlr Sub Hrs 0.50	Sub Labor Amt \$92.50
Serial#	Appr Hrs 0.30	Appr Labor Amt \$55.50
Notes TIME ADJUSTED TO MORE CLOSELY REFLECT REPAIR		

Submitted	Labor Amt \$462.50 Parts & Freight \$0.00	Approved	Labor Amt \$425.50 Parts & Freight \$0.00
------------------	--	-----------------	--

Total \$462.50

Total \$425.50

DEALER DATE

SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE

SIGNATURE
All repairs described have been inspected and are satisfactory.