



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78142
Promised Date:
24 OCT 25

CUSTOMER WORK ORDER

WO #: 78142

Customer: 7226 - GOURLEY, BOBBY L. - Stock #: 11456

812-618-6656

Tag:

Author: PH

Location: 1112 SEE IF BRM HAS
BROUGHT THIS IN YET

Stock Desc: 2025 TT COACHMEN

CATALINA 283RKSLE

Chassis #: 5ZT2CATB8SX032741

Serial #: 5ZT2CATB8SX032741

Mileage:

Licence:

Invoice #:

Date In: 24 OCT 25

Promised: 31 OCT 25

Date Sched:

Completed: 14 NOV 25

Warr. Date: 04 OCT 24

Job #1 - Warranty

COMPLAINT: LOOK AND FLOOR THAT IS COMING LOOSE

CAUSE: Some appears to have rolled under room when it ran in.

CORRECTION: Glued edges and sealed floor

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	92.50

Subtotal for Job #1: 92.50

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE SLIDE ROOM IS CROOKED WHEN IT IS OUT. SEE SERVICE HISTORY.

CAUSE: Noticed to top was out farther than the bottom. And not sealed on inside when out

CORRECTION: Checked on lower side and found the ram was already to furthest position on the frame and the adjustment nuts was already at the end of adjustment. We found the threaded end of the ram could be adjusted out. So i pulled the set screw and ran the thread out and reinstalled the set nut the reconnected ran to room and adjusted the bell stop. Ran room. In and out. And now room seals at the bottom. Pete looked at room and approved adjustments.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	9.25
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	268.25

Subtotal for Job #2: 277.50

Job #3 - Warranty

COMPLAINT: LOOK AT THE BACK SPLASH IT IS COMING LOOSE

CAUSE: Turned in request for parts

CORRECTION: removed the panel and cleaned off the old adheasive and installed new adheasive and installed on wall and sealed lower edge.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00



Customer #: 7226
GOURLEY, BOBBY L.

Parts

Part #	Description	Qty	Price	Total
F100604170	BACKSPLASH, 14 X 24 TL GRAY HARMONY	1.00	25.35	25.35

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-BACKSPLASH	1.00	15.83	15.83

Subtotal for Job #3: 96.68

Parts Total: 25.35
 Labour Total: 425.50
 Sublet Total: 0.00
 Extras Total: 15.83
WORK ORDER TOTAL: 466.68

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 Nov 2025

W/O: 78142
 Promised Date: 31 OCT 25



Customer #: 7226
 GOURLEY, BOBBY L.

