



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 78373  
Promised Date:  
07 NOV 25

## CUSTOMER WORK ORDER

WO #: 78373

Customer: 56358 - SCHUSTER, KEITH -  
615-533-5766

Tag:

Author: BH

Location: 1211 BH TO CLOSE

Stock #: 11515

Stock Desc: 2025 TT COACHMEN

FREEDOM EXPRESS 259FKDS

Chassis #: 5ZT2FERB7SW030507

Serial #: 5ZT2FERB7SW030507

Mileage: 0

Licence:

Invoice #: 425166

Date In: 06 NOV 25

Promised: 07 NOV 25

Date Sched:

Completed: 11 DEC 25

Warr. Date: 07 NOV 25

### Job #FPDINTT - Internal

Transferred to BAS\*78483 on 17 NOV 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

#### Labor

| Code   | Description              | Mechanic | Total |
|--------|--------------------------|----------|-------|
| PDINTT | PDI - NEW TRAVEL TRAILER | JTW      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | JTW      | N/C   |

Subtotal for Job #FPDINTT: 0.00

### Job #1 - Warranty

COMPLAINT: OVER THE SINK CABINET DOOR IS DAMAGED  
AND NEEDS REPLACED

CAUSE: New cabinet door replacement

CORRECTION: Opened the cabinet door and unscrewed it from the cabinet. Unscrewed the hinges and handle from the door. Opened the box with the new cabinet door. Transferred the hole measurements over to the new cabinet door from the damaged door. Drilled holes in the new cabinet door to accept the handle and hinges. Mounted the handle and hinges then screwed the cabinet door back on the cabinet. Opened and closed the door to check the fitment. Put the damaged door in the warranty department.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | SAR      | 74.00 |

#### Parts

| Part #     | Description                             | Qty  | Price | Total |
|------------|-----------------------------------------|------|-------|-------|
| F100608789 | DOOR, M & T MDF FPS 14" X 14"<br>SP1355 | 1.00 | 19.80 | 19.80 |

#### Other Services

| Code | Description | Qty  | Price | Total |
|------|-------------|------|-------|-------|
| FRT  | FREIGHT     | 0.00 | 0.00  | 0.00  |

Subtotal for Job #1: 93.80

### Job #2 - Warranty

COMPLAINT: THE BATHROOM DOOR HAS SOME DAMAGE ON IT THE CUSTOMER FOUND ONCE  
HE TOOK THE UNIT HOME

CAUSE: Bathroom door replacement with new door.

CORRECTION: Opened the bathroom door and unscrewed the door handle and the hinges. Moved the

Printed On: 12/11/2025 10:56:04AM

© 2025 Integrated Dealer Systems



Customer #: 56358  
SCHUSTER, KEITH



door handle to the new bathroom door and set the bathroom door in place. Screwed the door the the hinges. Opened and closed the bathroom door to check the fitment. Put the damaged door in the warranty department.

| Labor |                             |          |       |
|-------|-----------------------------|----------|-------|
| Code  | Description                 | Mechanic | Total |
| Z990  | MISC LABOUR CODE (EXTERNAL) | SAR      | 92.50 |

| Parts      |                                     |      |       |       |
|------------|-------------------------------------|------|-------|-------|
| Part #     | Description                         | Qty  | Price | Total |
| F100609445 | DOOR, BATH 1-3/8 X 21 X 78 HC W/CTR | 1.00 | 60.81 | 60.81 |

**Subtotal for Job #2: 153.31**

### Job #3 - Warranty

COMPLAINT: THE BED ROOM DOOR HAS SOME DAMAGE ON IT THAT THE CUSTOMER FOUND ONCE HE TOOK THE UNIT HOME

CAUSE: Replacement slid door for the bedroom

CORRECTION: Slid the bedroom door to the middle of the track then unclipped the glides from the top of the door. Set the door to the side and pulled out the metal finger holes from the center edge of the door. Unscrewed the glide clips from the top of the door and screwed them onto the new door. Set the slide door under the track and clipped on the track. Opened and closed the door to check the fitment. Put the door in the warranty department.

| Labor |                             |          |       |
|-------|-----------------------------|----------|-------|
| Code  | Description                 | Mechanic | Total |
| Z990  | MISC LABOUR CODE (EXTERNAL) | SAR      | 92.50 |

| Parts      |                                     |      |        |        |
|------------|-------------------------------------|------|--------|--------|
| Part #     | Description                         | Qty  | Price  | Total  |
| F100609449 | DOOR, SLIDER 1-3/8X23X78 SHAKER G2S | 1.00 | 137.58 | 137.58 |

**Subtotal for Job #3: 230.08**

### Job #TRIP - External

COMPLAINT: TRIP CHARGE TO CUSTOMER AND MILES LANDING

CAUSE: Drive to the camp ground and back

CORRECTION: Drive to the camp ground and back to preform a service

| Labor |                             |          |       |
|-------|-----------------------------|----------|-------|
| Code  | Description                 | Mechanic | Total |
| Z990  | MISC LABOUR CODE (EXTERNAL) | SAR      | N/C   |
| Z990  | MISC LABOUR CODE (EXTERNAL) | SAR      | N/C   |

| Other Services |               |      |       |       |
|----------------|---------------|------|-------|-------|
| Code           | Description   | Qty  | Price | Total |
| SS             | SHOP SUPPLIES | 1.00 | N/C   | N/C   |
| TRIP           | TRIP CHARGE   | 1.00 | N/C   | N/C   |

**Subtotal for Job #TRIP: 0.00**

Parts Total: 218.19  
 Labour Total: 259.00  
 Sublet Total: 0.00  
 Extras Total: 0.00

**WORK ORDER TOTAL: 477.19**



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 11 Dec 2025

W/O: 78373  
Promised Date: 07 NOV 25



Customer #: 56358  
SCHUSTER, KEITH



Customer Work  
Order

