

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78373
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 56358 - KEITH SCHUSTER
Address: 300 CEDAR BEND RD BEECHGROVE, TN

37018

Phone: 615-533-5766

Stock Number: 11515 - 2025 FREEDOM EXPRESS 259FKDS 5ZT2FERB7SW030507

VIN: 5ZT2FERB7SW030507 HIN: SER#: 5ZT2FERB7SW030507

Mileage: 0

Work Order Comp: 11 DEC 25

Auth. No:

Dealer #:

Warr. Date: 07 NOV 25

Work Order Date: 06 NOV 25

Inv #: 425167

WO # Job # Description JOB INFORMATION

78373 1 OVER THE SINK CABINET DOOR IS DAMAGED AND NEEDS REPLACED
New cabinet door replacement
Opened the cabinet door and unscrewed it from the cabinet.
Unscrewed the hinges and handle from the door. Opened the box
with the new cabinet door. Transferred the hole measurements over
to the new cabinet door from the damaged door. Drilled holes in
the new cabinet door to accept the handle and hinges. Mounted the
handle and hinges then screwed the cabinet door back on the
cabinet. Opened and closed the door to check the fitment. Put the
damaged door in the warranty department.

78373 2 THE BATHROOM DOOR HAS SOME DAMAGE ON IT THE CUSTOMER FOUND ONCE
HE TOOK THE UNIT HOME
Bathroom door replacement with new door.
Opened the bathroom door and unscrewed the door handle and the
hinges. Moved the door handle to the new bathroom door and set
the bathroom door in place. Screwed the door the the hinges.
Opened and closed the bathroom door to check the fitment. Put the
damaged door in the warranty department.

78373 3 THE BED ROOM DOOR HAS SOME DAMAGE ON IT THAT THE CUSTOMER FOUND
ONCE HE TOOK THE UNIT HOME
Replacement slid door for the bedroom
Slid the bedroom door to the middle of the track then unclipped
the glides from the top of the door. Set the door to the side and
pulled out the metal finger holes from the center edge of the

Claim : 78373

 WO # Job # Description JOB INFORMATION

door. Unscrewed the glide clips from the top of the door and
 screwed them onto the new door. Set the slide door under the
 track and clipped on the track. Opened and closed the door to
 check the fitment. Put the door in the warranty department.

 Part No Job# Description PARTS Qty Price Total

 F100609447 3 DOOR, SLIDER 1-3/8X23X78 W/CTR 3/ 0.00 75.61 0.00

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.40 185.00 74.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.50 185.00 92.50
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.50 185.00 92.50

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 FREIGHT 0.00 0.00 0.00

Parts Total: 0.00
 Labour Total: 259.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 259.00

Customer Signature: _____

Date: _____