



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78464
Promised Date:
21 DEC 25

CUSTOMER WORK ORDER

WO #: 78464

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 0305 SEE IF PARTS ARE
HERE YET

Stock #: 11530
Stock Desc: 2025 TT COACHMEN
FREEDOM EXPRESS 324RLDS
Chassis #: 5ZT2FEXB6SW030243
Serial #: 5ZT2FEXB6SW030243
Mileage: 0
Licence:

Invoice #:
Date In: 14 NOV 25
Promised: 31 DEC 25
Date Sched:
Completed: 28 FEB 26
Warr. Date: 09 MAR 26

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*78815 on 10 JAN 26

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Winterized unit and filled out checksheet. 2gl used.

Labor

| Code | Description | Mechanic | Total |
|------|----------------|----------|-------|
| Z990 | WINTERIZE UNIT | JRK | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|------|---------------|------|-------|-------|
| SS | SHOP SUPPLIES | 0.00 | N/C | N/C |

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: BEDROOM SLIDE WILL NOT CLOSE

CAUSE: Bad Limit Switch

CORRECTION: I winterized the unit and as i was closing up the unit, the Bedroom slideout did not retract in. Checked the switch and it has 12v power and power both ways on switch. Removed cover board under bed and motor panel. The motor is unplugged and currently hunting down the other end of plug...located the control box on the outside corner of the bed mounted carpet area by removeing the facial of carpeted platform. I found a small sensor white wire pinched in between 2 metal brackets. Spoke with Ben in regards to my findings. Ben requested that i get picks of both ends of sensor wire and controller. Working on closing slideroom so its tying up my bay for days while i wait for parts. Installed the old controller and tied the sensor wires together to bypass sensor and room retracted in with sputters. Received new Limit Switch. Disassembled the subfloor under bed and carpeted sidewall at floor to expose the areas needed to reach the Limit Switch mount inside of slideroom rail. Couldnt reach the inside to position and outside to screw into Switch so i had to remove the Slideroom Bed Frame and even then it was next to impossible to complete Switch replacement without disassembling th3 slideroom and Rail but i was able to thread a wire with an Eyenon the end and then thread wire thru th3 backside of mount in Rail. It took me a few times and repetition but got it ac. Reassembled the unit

Labor



Customer #: 1000
BASDENS AMERICAN RV,



| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|--------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 70.30 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 114.70 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 0.00 |

Parts

| Part # | Description | Qty | Price | Total |
|------------|--------------------------------------|------|-------|-------|
| F100680705 | HAPPIJAC SLIDE ROOM CONTROLLER ASSY | 1.00 | 70.79 | 70.79 |
| 183201 | HappiJac 2-Pin Slide-Out Microswitch | 1.00 | 20.80 | 20.80 |

Other Services

| Code | Description | Qty | Price | Total |
|------|----------------------|------|-------|-------|
| FRT | SLIDE CONTROLLER UPS | 1.00 | 15.87 | 15.87 |
| FRT | FED-EX- SWITCH | 1.00 | 10.83 | 10.83 |

Subtotal for Job #1: 303.29

Parts Total: 91.59
 Labour Total: 185.00
 Sublet Total: 0.00
 Extras Total: 26.70
WORK ORDER TOTAL: 303.29

Thank you for being a valued customer. We appreciate your business.
 All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature: _____

Date: 05 Mar 2026

W/O: 78464
 Promised Date: 31 DEC 25



Customer #: 1000
 BASDENS AMERICAN RV,

