

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78475
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 56066 - KATHLEEN BEMONT
Address: 407 E EMMONS ST
ROBINSON, IL
62454

Phone:

Stock Number: 2026 CAMPSIGHT

VIN:

Mileage:

Auth. No:

Warr. Date:

HIN:

SER#: 5ZT2CRRB7TF081717

Work Order Comp: 19 NOV 25

Dealer #:

Work Order Date: 15 NOV 25

Inv #: 424720

WO # Job # Description JOB INFORMATION

78475 2 SMALL LEAK UNDER THE BACK THE BATH ROOM SINK AT VACUUM BREAKER
The inlet to the vacuum breaker is missing the gasket screen on
the outside. Hooked up the water hose and ran water through the
vacuum. Both ends of the breaker are leaking and it is leaking
internally.
Replaced outside the gasket screen. The supply line is has
different cone washers that the rest of the unit. Replaced the
supply line with a new hose that has the " normal" cone washers
installed. The replacement vacuum breaker is leaking internally.
Went to another style of vacuum breaker. Tested and secured the
vacuum breaker to the wall. All leaks have been fixed. Cleaned up
area.

Part No Job# Description PARTS Qty Price Total

ESC06435 2 CONE WASHER SWIVEL SEAL 1.00 0.23 0.23
BRV113704 2 FITTING-RISER W/SWIVEL ELBOWS 1.00 8.15 8.15
CMC20183 2 20183 3-PK 1" HOSE FILTERS 1.00 3.95 3.95
23-0328 2 VACUUM BREAKER 1.00 17.33 17.33
ESC51177 2 1/2" BARB X 1/2 FPT SWIVEL CONE 1.00 2.24 2.24
BBM94239 2 94239 VACUUM BREAKER/CHECK VALVE 1.00 22.62 22.62

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 185.00 55.50

Claim : 78475

Lab Code Job# Description LABOUR Hrs Rate Total

Parts Total: 54.52
Labour Total: 55.50
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 110.02

Customer Signature: _____

Date: _____