

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2506686
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CRRB7TF081717
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	086 / 086B
OWNER INFORMATION		ITEM #	CRT26CJ-86
KATHLEEN BEMONT		DEALER RO #	78475
407 E EMMONS ST		CLAIM START DATE	11/20/2025
Robinson, IL 62454		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	07/08/2025	WARRANTY EXPIRATION DATE	07/08/2026

Claim Line Details

Labor

Line#	Operation Code	Operational Description
1	60-138-01-00-001537	Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-11-20 12:25:35 :: CAMPER HAS A LEAK UNDER THE CAMPER CUSTOMER PULLED OUT AND SAW WATER FALLING FROM UNDER THE CAMPER Ran water through all lines and fixtures. The water lines and plumbing lines were also tested during the other jobs. I didn't see any signs of a leak. I believe the water was from the black tank flush/ vacuum breaker leaking. The vacuum breaker and the lines leaking were the only leaks found. This was repaired in the other job. The inlet to the vacuum breaker is missing the gasket screen on the outside. Hooked up the water hose and ran water through the vacuum. Both ends of the breaker are leaking and it is leaking internally. Replaced outside the gasket screen. The supply line is has different cone washers that the rest of the unit. Replaced the supply line with a new hose that has the " normal" cone washers installed. The replacement vaccum breaker is leaking internally. Went to another style of vacuum breaker. Tested and secured the vacuum breaker to the wall. All leaks have been fixed. Cleaned up area.

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$74.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50

Notes

pleas attach pictures of the Replaced outside the gasket screen thank you
PHOTOS ADDED
please replace gasket screen thank you

Submitted	Labor Amt	\$74.00	Approved	Labor Amt	\$55.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$74.00		Total	\$55.50

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2506686
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CRRB7TF081717
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	086 / 086B
Labor rate:	\$185.00	ITEM #	CRT26CJ-86
OWNER INFORMATION		DEALER RO #	78475
KATHLEEN BEMONT		CLAIM START DATE	11/20/2025
407 E EMMONS ST		CLAIM END DATE	01/01/1900
Robinson, IL 62454			
USA			
Retail Date of Purchase	07/08/2025	WARRANTY EXPIRATION DATE	07/08/2026

Claim Line Details

Labor

Line#	Operation Code	Operational Description
1	60-138-01-00-001537	Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-11-20 12:25:35 :: CAMPER HAS A LEAK UNDER THE CAMPER CUSTOMER PULLED OUT AND SAW WATER FALLING FROM UNDER THE CAMPER Ran water through all lines and fixtures. The water lines and plumbing lines were also tested during the other jobs. I didn't see any signs of a leak. I believe the water was from the black tank flush/ vacuum breaker leaking. The vacuum breaker and the lines leaking were the only leaks found. This was repaired in the other job. The inlet to the vacuum breaker is missing the gasket screen on the outside. Hooked up the water hose and ran water through the vacuum. Both ends of the breaker are leaking and it is leaking internally. Replaced outside the gasket screen. The supply line is has different cone washers that the rest of the unit. Replaced the supply line with a new hose that has the " normal" cone washers installed. The replacement vaccum breaker is leaking internally. Went to another style of vacuum breaker. Tested and secured the vacuum breaker to the wall. All leaks have been fixed. Cleaned up area.

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$74.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50

Notes

pleas attach pictures of the Replaced outside the gasket screen thank you
PHOTOS ADDED
please replace gasket screen thank you

Submitted	Labor Amt	\$74.00	Approved	Labor Amt	\$55.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$74.00		Total	\$55.50

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____

All repairs described have been inspected and are satisfactory.