



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78480



CUSTOMER WORK ORDER

WO #: 78480 (Appointment Date: 15 NOV 2025 - Time: 03:00pm)
 Customer: 55561 - HARRIS, JOSHUA-SHANE - 812-598-5531
 Tag: Author: GA Location: 1126 BH TO CLOSE
 Stock #: 11434
 Stock Desc: (11434) 2025 FOREST RIVER CHEROKEE GREY WOLF 29NM
 Chassis #: 4X4TCKE29SK091023
 Serial #: 4X4TCKE29SK091023
 Mileage:
 Licence:
 Invoice #:
 Date In: 15 NOV 25
 Promised:
 Date Sched:
 Completed: 24 NOV 25
 Warr. Date: 27 FEB 25

Job #1 - Warranty

COMPLAINT: ROOF HAS BUBBLE AND AREA WHERE NOT SEALED

CAUSE: One minor bubbled area

CORRECTION: Inspected roof membrane and found one area with bubbling but this is not a issue to be worried on.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: WHEN SHUTTING THE REAR ENTRY DOOR YOU HAVE TO REALLY SLAM IT OR IT WONT STAY SHUT OR HAVE TO USE DEAD BOLT

CAUSE: Striker plate bent and already adjusted all the way out.

CORRECTION: Modified new striker plate to adjust out further.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: middle of the awning leaks by the 2 awning rails needs to be sealed

CAUSE: Gutter was clogged and leaking at seam between the 2 gutters coming together.

CORRECTION: Inspected area of leaking gutter and found build up of Dirt/mud on top of manufacturer dicor was too much and gcreating a dam. Cleaned gutter and removed the clump of Dicor. Resealed with black dicor.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00

Customer #: 55561
HARRIS, JOSHUA-SHANE



Subtotal for Job #3: 37.00

Job #4 - Warranty

COMPLAINT: CUSTOMER THINKS SLIDE MAY BE OUT OF ADJUSTMENT. WHEN RUNNING IN ONE SIDE CAME IN ALL THE WAY AND THE OTHER STUCK OUT 6-8 INCHES.

CAUSE: System was out of sync.

CORRECTION: Removed front lower board of dinnette looking for the Cable Adjustments but wasn't there, put it back. Removed the dinnette seating board and it wasn't there either. Zach helped and advised me on resetting the controlbox for the drive system to resync the pullie system. Located the controlbox behind the Main Switch control panel. Reset the controlbox and tested the slideroom, all is working properly and within the specs. Remounted controlbox and panel.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	92.50

Subtotal for Job #4: 92.50

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES DICOR ON ROOF IS COMING LOOSE AND IS SPREADING APART

CAUSE: Some voids and thin dicor areas...

CORRECTION: Inspected roof and found a few voids but overall the dicor is fairly thin. Will let Ben speak to manufacturer to see what direction they advise. Ben informed me that Manufacturer approved 4hrs and 15 tubes. Retrieved the 15 tubes. Used crown to scrub all thinned areas and sprayed the areas off with the hose and pulled inside to dry the next 2 days. Applied all areas on Rooftop with thicker dicor at all screws and seams of installs.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	370.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	185.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	15.00	8.72	130.80

Subtotal for Job #5: 870.80

Job #6 - Internal

COMPLAINT: CHECK VACUUM BREAKER

CAUSE: No issues with Vacuum Breaker.

CORRECTION: Hooked up hose to black tank flush and turned on water pressure and checked the vacuum breaker for any leaks and all areas of vacuum breaker is dry.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #6: 0.00

W/O: 78480



Customer #: 55561
HARRIS, JOSHUA-SHANE



Parts Total: 130.80
Labour Total: 906.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 1,037.30

W/O: 78480

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 24 Nov 2025

Customer Signature : _____

Customer Work Order



Customer #: 55561
HARRIS, JOSHUA-SHANE

