

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2530702
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAZBXTX036377
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT343BHTSLE
		DEALER RO #	78490
		CLAIM START DATE	12/17/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code	20-44-19-00-000553	Operational Description
		Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-12-17 13:55:24 :: LOOSE DICOR ON ROOF. NOT SEALING Loose dicor on roof During pdi noitced dicor was loose on roof at doorside front cap. Cut off dicor that was not sealing and added new dicor to fill void.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 3

Operation Code	40-196-01-11-001274	Operational Description
		Single Pancake Light - Electrical/12 Volt Interior/Replace/Electrical
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-12-17 13:59:40 :: LIGHT ABOVE DINNETT DOESN'T WORK Dinnet light not work. During pdi i noticed the light above the dinnet would not come on even after mutpliple tries. Parts request submitted		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 4

Operation Code	20-58-01-00-000608	Operational Description
		Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Replace/ No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-12-17 14:00:16 :: SCRATCH ON BEDROOM SLIDEROOM METAL Scartches on slideroom metal, bent slideroom exterior trim During pdi i noticed the metal on the bedroom slide had multiple scratches. Wlso during pdi noticed the trim on the slideroom had a bend in the metal. Pictures taken parts request submitted.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	4.00	\$740.00
Serial#	Appr Hrs	Appr Labor Amt
	4.00	\$740.00
Notes		
AUTHORIZED AS REQUESTED		

Labor

Line# 5

Operation Code	20-43-24-00-000589	Operational Description
		Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Repair/No Tread Code
Complaint, Cause, Correction		

Original Note : bhoffman@americanrvcenter.com, 2025-12-17 14:00:50 :: DECAL ON LIVING ROOM SLIDE HAS BUBBLES Bubbles in decal on slideroom During pdi I noticed the decals on the living room slideroom had bubbles in them. Made a small hole and pushed the air out of the holes on the decals. Decals no longer have bubbles in them

Model#	Dir Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00

Notes
AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$851.00	Approved	Labor Amt	\$851.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$851.00		Total	\$851.00

DEALER _____ **DATE** _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
All repairs described have been inspected and are satisfactory.