



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78490
Promised Date:
24 DEC 26

CUSTOMER WORK ORDER

WO #: 78490

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0121 CHECK STATUS WITH
SAR

Stock #: 11675
Stock Desc: 2026 TT COACHMEN
CATALINA 343BHTSLE
Chassis #: 5ZT2CAZBXTX036377
Serial #: 5ZT2CAZBXTX036377
Mileage:
Licence:

Invoice #:
Date In: 17 NOV 25
Promised: 31 DEC 25
Date Sched:
Completed: 22 JAN 26
Warr. Date: 20 NOV 25

Job #PDINTT - Internal

Transferred to BAS*78790 on 06 JAN 26
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

Transferred to BAS*78790 on 06 JAN 26
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	CCV	N/C
Z990	WINTERIZE UNIT	CCV	N/C
Z990	WINTERIZE UNIT	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: LOOSE DICOR ON ROOF. NOT SEALING

CAUSE: Loose dicor on roof



Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: During pdi noticed dicor was loose on roof at doorside front cap. Cut off dicor that was not sealing and added new dicor to fill void.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #1: 37.00

Job #2 - Internal

COMPLAINT: FRIDGE IS NOT PROPERLY SECURED

CAUSE: NO ISSUES FOUND

CORRECTION: During pdi noticed the fridge was not properly secured.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: LIGHT ABOVE DINNETT DOESN'T WORK

CAUSE: Dinnet light not work.

CORRECTION: During pdi i noticed the light above the dinnet would not come on even after mutiple tries.
Parts request submitted

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50

Parts

Part #	Description	Qty	Price	Total
12150	3.5 INCH LED LIGHT PUCK BASE WITH LE	1.00	2.05	2.05

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT JOBS 3,4	1.00	232.75	232.75

Subtotal for Job #3: 271.80

Job #4 - Warranty

COMPLAINT: SCRATCH ON BEDROOM SLIDEROOM METAL

CAUSE: Scartches on slideroom metal, bent slideroom exterior trim

CORRECTION: During pdi i noticed the metal on the bedroom slide had multiple scratches. Wlso during pdi noticed the trim on the slideroom had a bend in the metal. Pictures taken parts request submitted.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	166.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	57.35
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	122.10
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	340.40
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	53.65
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00





Parts				
Part #	Description	Qty	Price	Total
C01256654	MOLDING, T-BAR EXTERIOR 4 1/2"BLACK	1.00	30.55	30.55
12151	METAL, .024 X 12 X 156 1MDM SL MET S	2.00	36.62	73.24
GC66100	Geocel 2300 Construction Tripolymer	1.00	13.35	13.35
F100359506	SILICONE, NEUTRAL CURE SILICONE 10.3	1.00	13.66	13.66

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-METAL	1.00	558.14	558.14

Subtotal for Job #4: 1,428.94

Job #5 - Warranty

COMPLAINT: DECAL ON LIVING ROOM SLIDE HAS BUBBLES

CAUSE: Bubbles in decal on slideroom

CORRECTION: During pdi I noticed the decals on the living room slideroom had bubbles in them. Made a small hole and pushed the air out of the holes on the decals. Decals no longer have bubbles in them

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #5: 37.00

Parts Total: 132.85
 Labour Total: 851.00
 Sublet Total: 0.00
 Extras Total: 790.89
WORK ORDER TOTAL: 1,774.74

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Jan 2026

