

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78534
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11679 - 2026 CATALINA 281QBUNK 5ZT2CATB8TN302287

VIN: 5ZT2CATB8TN302287 HIN:

SER#: 5ZT2CATB8TN302287

Mileage: 0

Work Order Comp: 12 DEC 25

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 21 NOV 25

Inv #: 425073

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

78534	3	HOLE IN UNDER BELLY Underbelly was cut and opened up On my inspection of the underneath of the camper i found that the underbelly was cut and hanging down. So i secured it back up with some underbelly tape. And unit is good now	
78534	4	OFF DOOR SIDE SLIDE WINDOW SEAL IS COMING OUT Window glazing not seated Pushed the window glazing back i. The track and made sure it was seated properly good to go now	
78534	5	THERE IS NOTHING COMING FROM THE VENTS ON THE FLOOR No heat coming out of the registers After inspection of the furnace i found that the duct work coming from the furnace to the main duct work that runs down the camper to the registers wasn't cut out from the factory. So i pulled the furnace and took pictures and Ben sent it to the factory and they told us how they wanted us to fix this issue. So i went to the underbelly and found the duct work by the measurements they gave us and i made cuts in the underbelly and i took the tape off the duct work and cut 2 sections out of the duct work that ran from the furnace to the main duct work. And once i did that i re taped the main duct work back with aluminum duct tape. Then i put the underbelly insulation and taped up my cuts in the underbelly with underbelly tape. Then i came inside unit and re installed the furnace and lp line then i checked my connection with leak spray.	

Claim : 78534

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

No leaks. Then i turned the furnace on and all the registers had heat coming from them. Then i put up all the trim pannels that i took off during the furnace inspection. And i cleaned my mess up. Unit good to go now

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
----------	------	-------------	--------	-----	------	-------

Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		1.80	185.00	333.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		3.20	185.00	592.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
--------	------	-------------	--------	-----	-------	-------

SS	5	SAW BLADE INSULATION UNDER BELLY TAPE		1.00	70.00	70.00
----	---	---------------------------------------	--	------	-------	-------

Parts Total:	0.00
Labour Total:	999.00
Sublet Total:	0.00
Extras Total:	70.00

>>>> Claim Total: 1,069.00

Customer Signature: _____

Date: _____