

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2517502
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CATB8TN302287
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	300 / 300
Labor rate:	\$185.00	ITEM #	CAT281QBUNK-8-300
OWNER INFORMATION		DEALER RO #	78534
		CLAIM START DATE	12/03/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase	WARRANTY EXPIRATION DATE
--------------------------------	---------------------------------

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	10-9-15-00-000168	Polymax Underbelly - Frame & Chassis/Levelers, Underbelly/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-12-03 15:17:26 :: HOLE IN UNDER BELLY Underbelly was cut and opened up On my inspection of the underneath of the camper i found that the underbelly was cut and hanging down. So i secured it back up with some underbelly tape. And unit is good now			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			
	PHOTOS REQUIRED photos have been added done know why they were not AUTHORIZED AS REQUESTED			
Labor				
Line# 2	Operation Code	Operational Description		
	20-46-19-00-000721	Window - Exterior/Windows/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-12-03 15:18:08 :: OFF DOOR SIDE SLIDE WINDOW SEAL IS COMING OUT Window glazing not seated Pushed the window glazing back i. The track and made sure it was seated properly good to go now			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			
Labor				
Line# 3	Operation Code	Operational Description		
	70-507-24-00-002111	Furnace Duct - Appliances/Ducting/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-12-03 15:18:32 :: THERE IS NOTHING COMING FROM THE VENTS ON THE FLOOR No heat coming out of the registers After inspection of the furnace i found that the duct work coming from the furnace to the main duct work that runs down the camper to the registers wasn't cut out from the factory. So i pulled the furnace and took pictures and Ben sent it to the factory and they told us how they wanted us to fix this issue. So i went to the underbelly and found the duct work by the measurements they gave us and i made cuts in the underbelly and i took the tape off the duct work and cut 2 sections out of the duct work that ran from the furnace to the main duct work. And once i did that i re taped the main duct work back with aluminum duct tape. Then i put the underbelly insulation and taped up my cuts in the underbelly with underbelly tape. Then i came inside unit and re installed the furnace and lp line then i checked my connection with leak spray. No leaks. Then i turned the furnace on and all the registers had heat coming from them. Then i put up all the trim pannels that i took off during the furnace inspection. And i cleaned my mess up. Unit good to go now			
Model#	Dlr Sub Hrs	5.00	Sub Labor Amt	\$925.00

Serial#

Appr Hrs5.00

Appr Labor Amt\$925.00

Notes

AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$999.00	Approved	Labor Amt	\$999.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$999.00		Total	\$999.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.