



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78410



Customer #: 49494
WARNER, JR., HOWARD L.



CUSTOMER WORK ORDER

WO #: 78410 (Appointment Date: 08 NOV 2025 - Time: 09:00am)

Customer: 49494 - WARNER, JR.,

HOWARD L. - 270-244-0623

Tag:

Author: BH

Location: 1128 CHECK WORK

Stock #: 11470

Stock Desc: 2025 TT ALLIANCE RV

DELTA 281BH

Chassis #: 7M5TD3122SC304351

Serial #: 7M5TD3122SC304351

Mileage: 0

Licence:

Invoice #: 424769

Date In: 08 NOV 25

Promised:

Date Sched:

Completed: 26 NOV 25

Warr. Date: 03 MAY 25

Job #1 - Warranty

COMPLAINT: WATER QUICK CONNECT WILL NOT CONNECT TO HOSE ON ALL OF THE HOSES

CAUSE: Spray port connections are sticky

CORRECTION: Got the spray port hose then was firm about connecting the spray port hose to all three spray port connections. Took pictures of each connection. Then when winterizing the two spray ports in the front compartment would leak when the water pump was on. Got two new spray ports from the parts department. Unscrewed the bad spray ports then screwed on the new spray ports and passed antifreeze through them. The spray port at the rear was not leaking. Put bad spray ports in warranty department.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	74.00

Parts

Part #	Description	Qty	Price	Total
24404	Spray Port - O/S w/Metal MPT Connect	2.00	9.83	19.66

Subtotal for Job #1: 93.66

Job #2 - Internal

COMPLAINT: BLACK WATER FLUSH DOESN'T WORK. FLOODS UNDER BATHROOM SINK

CAUSE: Stink bugs and ball valve was jammed

CORRECTION: Went to the bathroom sink then unscrewed the vacuum breaker from the water lines. Opened the vacuum breaker and found stink bugs inside and the ball valve was stuck. Got a replacement vacuum breaker and then installed it. Connected a garden hose to the black tank flush connection to verify the vacuum breaker wasn't leaking, no leaks occurred.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	1.00	N/C	N/C



Job #3 - Warranty

COMPLAINT: CARPET ON SLIDE ROOM IS ROLLING UP CUSTOMER PUT A BOOK ON THE CARPET AND IT WOULD NOT STAY DOWN

CAUSE: Not carpet it's linoleum. Linoleum is hitting the screw behind the slideroom fascia.

CORRECTION: Ran the slideroom out and took pictures of the slideroom linoleum on the left-hand side. Checked the screw behind the slideroom fascia as the linoleum was hitting it. Ran the slideroom in a little and picked up the linoleum and found a dent in the linoleum where it was hitting the screw. Trimmed back the linoleum till it didn't hit the screw causing it to bunch up the linoleum. Used the heat gun to help relax the linoleum.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	74.00

Subtotal for Job #3: 74.00

Job #4 - Internal

COMPLAINT: SPEAKERS ON INSIDE OF CAMPER WON'T COME ON THE TV REMOTE IS IN THE ARM REST

CAUSE: The Bluetooth radio wasn't connected to the TV though the settings and speaker A need to be on.

CORRECTION: Turned on the TV with the remote. Turned on the Bluetooth radio then went through the settings on the TV then pushed the TV button and speaker A had sound come through the speaker in the ceiling.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #4: 0.00

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

CAUSE: Winterizing 2 gallons

CORRECTION: Drained the black, grey, and fresh tanks. Turned the valve at the water pump then added 2 gallons through the kitchen faucet, bathroom faucet, toilet, shower, and spray port x3. Depressed the city water connection and water heater.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	SAR	N/C
Z990	WINTERIZE UNIT	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00



Customer #: 49494
WARNER, JR., HOWARD L.



Job #5 - Warranty

COMPLAINT: THE KITCHEN FAUCET IS LOOSE

CAUSE: The base of the faucet is solid but the rest is wobbly

CORRECTION: Inspected the kitchen faucet and checked the base for firmness. The base of the faucet was tight and the rest above the base is wobbly. Put in po for warranty for a new kitchen faucet.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
24212	Faucet - Kitchen - Bullet Pulldown -	1.00	55.09	55.09

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- FAUCET	1.00	12.56	12.56

Subtotal for Job #5: 160.15

Parts Total: 74.75
Labour Total: 240.50
Sublet Total: 0.00
Extras Total: 12.56
WORK ORDER TOTAL: 327.81

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Nov 2025

W/O: 78410

Customer #: 49494
WARNER, JR., HOWARD L.