

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2541258
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAGC2SU046171
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	103 / 103
Labor rate:	\$185.00	ITEM #	CAT184BHSX
OWNER INFORMATION		DEALER RO #	78704
		CLAIM START DATE	01/05/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-102-15-00-003365	Operational Description Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-05 11:51:50 :: SLIDEROOM WALL BOARD RIGHT SIDE LOOSE Wall panel is loose. Secured panel with Brad nails and filled holes with putty.	
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$18.50
Serial#	Appr Hrs 0.10	Appr Labor Amt \$18.50
	Notes	

Labor

Line# 2	Operation Code 40-196-24-11-001297	Operational Description Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-05 11:52:21 :: WIRES SHOWING UNDER SLIDE ROOM Wire is loose under slide room. Secured wire with a zip tie.	
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$18.50
Serial#	Appr Hrs 0.10	Appr Labor Amt \$18.50
	Notes AUthorized as Requested	

Labor

Line# 3	Operation Code 30-102-15-00-003365	Operational Description Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-05 11:58:37 :: BATHROOM WALL BOARD LOOSE Wall panel is loose. Secured panel with Brad nails and filled holes with putty.	
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$18.50
Serial#	Appr Hrs 0.10	Appr Labor Amt \$18.50
	Notes	

Labor

Line# 4	Operation Code 30-102-15-00-003365	Operational Description Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-05 11:59:24 :: WALL BOARD ON THE TOP BUNK LOOSE The wall panel is loose. Secured panel with Brad nails and filled holes with putty.	
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$18.50

Serial#

Appr Hrs

0.10

Appr Labor Amt \$18.50

Notes

Labor

Line# 5

Operation Code

30-102-15-00-003365

Operational Description

Operational Description
Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code

Complaint, Cause, Correction

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-01-05 12:01:11 :: WALL BOARD ON THE BOTTOM BUNK
LOOSE The wall panel is loose. Secured panel with Brad nails and filled holes with putty.
Sub Labor Amt \$18.50

Original Note: bhornham@america.com
LOOSE The wall panel is loose. Secured panel with Brad nails and filled holes with putty.
 Sub Labor Amt \$18.50

Model#

Dlr Sub Hrs

0.10

Sub Labor Amt \$18.50

Serial#

Appr Hrs

0.10

Appr Labor Amt\$18.50

Notes

Submitted

Labor Amt

\$92.50

Parts & Freight

\$0.00

Total

\$92.50

Approved

Labor Amt

\$92.50

Parts & Freight

\$0.00

Total

\$92.50

DEALER

DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.