

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2532780
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKFC5TY039054
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	095 / 095A
OWNER INFORMATION		ITEM #	CKT17SC-95
		DEALER RO #	78708
		CLAIM START DATE	12/19/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor
Line# 1

Operation Code	70-148-01-00-001701	Operational Description	Speaker - Appliances/Radio/Replace/No Tread Code
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-12-19 11:56:58 :: OUTDOOR SPEAKERS BROKEN FROM INSTALL SCREWS WERE TOO TIGHT The plastic housing on both speakers are cracked. Needs replaced. REPLACE BOTH SPEAKERS			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$74.00
Serial#	Appr Hrs	0.40	Appr Labor Amt \$74.00
Notes			
All Dealers must submit pictures of the front and back of the speaker(s) for Vendor indentification purposes			

Labor
Line# 2

Operation Code	20-46-01-13-000730	Operational Description	Window Glazing, Seal - Exterior/Windows/Replace/Visibility
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-12-19 11:57:50 :: DOOR SIDDE WINDOW GIMP IS LOOSE The corner of the window gimp is damaged and needs replaced. REPLACE THE WINDOW HIMP			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$55.50
Notes			

Labor
Line# 3

Operation Code	20-69-24-00-000699	Operational Description	Compartment Door Frame - Exterior/Compartment Doors/Repair/No Tread Code
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-12-19 11:58:29 :: SLIDE OUT COMPARTMENT DOOR RUBS The door is hitting the frame. Took a hammer and a block of wood and moved the frame from the door and the hinge away from the frame. The door now clears.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
Notes			
code requires pictures of the issue for warranty review or coverage thank you missed that one thank you thank you			

Labor
Line# 4

Operation Code	30-100-02-00-003062	Operational Description	Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-12-19 11:59:28 :: BATHROOM CABINET DOORS RUB The			

