

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2544365
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKE29TK097079
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	094 / 094A
Labor rate:	\$185.00	ITEM #	CKT29NM-94
OWNER INFORMATION		DEALER RO #	78712
		CLAIM START DATE	01/07/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description	
	20-66-02-17-000672	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2026-01-07 16:03:45 :: BATH TO LIVING DOOR STRICKER TO HIGH Bathroom door to living area won't stay closed After inspection of the door i found that the striker was not adjusted correctly. So i adjusted it and had to adjust the hole thhat factory put in wrong location. Door works properly now		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
	Notes		

Labor

Line# 2	Operation Code	Operational Description	
	30-101-24-00-001079	Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2026-01-07 16:04:37 :: BATH TO BED SLIDING DOOR FLOOR TRACK BROKEN Bathroom door slide guide broke Inspection of the door slide guide found that it is broken. So i put in a parts request for a new one got the part in so i got it installed		
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$55.50
	Notes		

Labor

Line# 3	Operation Code	Operational Description	
	30-102-24-00-001094	Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2026-01-07 16:05:19 :: BOTTOM CABINET LEFT OF BED SCREW POKING THREW WALL Screw sticking out of closet Took the long screw out and put a shorter screw in its place. Good to go now		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
	Notes		

Submitted

Labor Amt	\$129.50
Parts & Freight	\$0.00
Total	\$129.50

Approved

Labor Amt	\$129.50
Parts & Freight	\$0.00
Total	\$129.50

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.