



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78713
Promised Date:
24 DEC 25



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 78713

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0127 CHECK STATUS WITH
JRK

Stock #: 11638
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE WOLF PUP 17SC
Chassis #: 5ZT2CKFC7TY039024
Serial #: 5ZT2CKFC7TY039024
Mileage: 0
Licence:

Invoice #:
Date In: 18 DEC 25
Promised: 31 DEC 25
Date Sched:
Completed: 28 JAN 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: BATHROOM CABINET DOORS RUBS HARD TO CLOSE

CAUSE: Cabinet doors are even and rubs when shut.

CORRECTION: Adjusted the hinges on on side.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	18.50

Subtotal for Job #1: 18.50

Job #2 - Warranty

COMPLAINT: HOSE BROKEN UNDER SINK

CAUSE: Vacuum breaker hose connection is broken

CORRECTION: Removed hose and vacuum breaker. Spoke with Ben, was told to replace them. Spoke with Chandler in parts and he retrieved both for me. Installed them back into position.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	55.50

Parts

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	1.00	22.62	22.62
BRV113704	FITTING-RISER W/SWIVEL ELBOWS	1.00	8.15	8.15

Subtotal for Job #2: 86.27

Job #3 - Internal

COMPLAINT: LOT ROT CABINET DOOR ABOVE BED BROKEN

CAUSE: Damaged cabinet door and face board

CORRECTION: Looks like Door was installed in the wrong position and then moved with longer screws and damaged other pieces of the face boards about the bed. 2nd cabinet door is warped/bent. Putting in part request to just rebuild the whole assembly. 2 1/2in wide x 5/8in thick x 87in lenght rounded on one side. 2 1/2in wide x 5/8in thick x 8 3/4in lenght.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C



Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
F100692740	STILE, 5/8" X 2 1/2" X 9' RADIUS STI	2.00	N/C	N/C
F100683827	STILE, 5/8" X 2-1/2" X 9' SE STILE 1	1.00	N/C	N/C
F100681815	PANELING, 5/32 X 48" X 96" TAYLOR CH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - PANELING	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: WINTER WALLS ARE DOWN AND NEEDS TO BE REINSTALLED

CAUSE: Winterize access panels were left down

CORRECTION: Reinstalled Winterizing panels.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: BED TO BATH LEFT DOOR TRIM TOP

CAUSE: Both sides of Door frame are damaged

CORRECTION: Inspected and measured damaged plastic frame between bedroom and bathroom. 3in wide, 1/2in lip on both sides, 155in in length (77 1/2in x 2 pieces).

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Parts

Part #	Description	Qty	Price	Total
30I78736A	MOLDING, 2-7/8" X 8' U-CHANNEL, 1022	1.00	4.25	4.25

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-MOLDING	1.00	171.43	171.43

Subtotal for Job #5: 231.18

Job #6 - Warranty

COMPLAINT: TAPE ON THE ENTRY STEPS

CAUSE: Grip tape on steps are damaged

CORRECTION: Measured 2in x 18in grip tape part requested. Received new grip tape strip from parts. Removed damaged tape from steps and cleaned adhesive and installed new strip.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	27.75
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	9.25



W/O: 78713
Promised Date: 31 DEC 25



Customer #: 1000
BASDENS AMERICAN RV,



Parts

Part #	Description	Qty	Price	Total
90M38913A	STEP, ABRASIVE SKID/TREAD TAPE - 2"	1.00	3.90	3.90

Subtotal for Job #6: 40.90

Job #7 - Warranty

COMPLAINT: CABINET ABOVE KITCHEN SINK WALL DOWN

CAUSE: Inside cabinet a false was was just laying and not installed.

CORRECTION: Measured and attached support boards on panel and installed in cabinet.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	55.50

Subtotal for Job #7: 55.50

Parts Total: 38.92
Labour Total: 222.00
Sublet Total: 0.00
Extras Total: 171.43

WORK-ORDER TOTAL: 432.35

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature: _____

Date: 28 Jan 2026

