



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78714
Promised Date:
24 JAN 26



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 78714

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0121 BH TO CLOSE

Stock #: 11612
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE GREY WOLF 27GH
Chassis #: 4X4TCKC26TK096118
Serial #: 4X4TCKC26TK096118
Mileage: 0
Licence:

Invoice #:
Date In: 18 DEC 25
Promised: 31 JAN 26
Date Sched:
Completed: 21 JAN 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: REAR COMPARTMENT CARPET HAS HOLES

CAUSE: Holes in carpet

CORRECTION: Noticed holes in rear compartment carpet. Parts request submitted

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	407.00

Parts

Part #	Description	Qty	Price	Total
F100321570	CARPET, 8' X LENGTH, DA01 1010 SMOKE	4.00	N/C	N/C
F100756596	CARGO LINER, 49" X LENGTH, (SOLD PER	12.00	1.51	18.12

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-CARPET	1.00	N/C	N/C
FRT	UPS-CARGO LINER	1.00	46.52	46.52

Subtotal for Job #1: 527.14

Job #2 - Warranty

COMPLAINT: BELOW KITCHEN SINK DOORS RUB

CAUSE: Undersink doors hitting

CORRECTION: Brought unit in. Saw undersink doors were rubbing against each other. Removed top screws from door hinge and adjusted hing over and secured to facia. Doors nonlonger hit

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Subtotal for Job #2: 18.50

Job #3 - Warranty

COMPLAINT: BEDROOM ENTRY DOOR NOT CLOSING FROM INSIDE



CAUSE: Door not closing

CORRECTION: Brought unit in. Went to back entry door and noticed it was not closing properly. Adjusted striker plate. Door shuts but still not adjusted properly. Used a hammer and a piece of wood to hit on door frame on side of hinges. Door appeared to be sucked in too much to shut properly. Striked door by hinges to force frame back over. Door shuts properly now.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Subtotal for Job #3: 55.50

Job #4 - Warranty

COMPLAINT: MIDDLE COMPARTMENT DOOR WILL NOT OPEN

CAUSE: Loose latch

CORRECTION: Took pictures showing i wasnt able to open the compartment door. Used a long rod to reach inside to move the latch. Once the door opened the latch and screw had fell off. Put the latch back on and tightened. Verified the door latch still opened after fix.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	18.50

Subtotal for Job #4: 18.50

Parts Total:	18.12
Labour Total:	555.00
Sublet Total:	0.00
Extras Total:	46.52
WORK ORDER TOTAL:	619.64

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Jan 2026

W/O: 78714
Promised Date: 31 JAN 26



Customer #: 1000
BASDEN'S AMERICAN RV,

