

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2532685
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKC21TX166918
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	017 / 017A
Labor rate:	\$185.00	ITEM #	ACKT27LH
OWNER INFORMATION		DEALER RO #	78716
		CLAIM START DATE	12/19/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-102-01-00-001101	Operational Description Slide Out Fascia, each section - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-12-19 11:10:18 :: LIVING ROOM SLIDE FACIA LOOKS LIKE IT WAS WET BEFORE Check with warranty on repair. what is recommended for this repair have not found water and unit was water tested and no water was found		
Model#	Dlr Sub Hrs 1.00	Sub Labor Amt \$185.00
Serial#	Appr Hrs 0.50	Appr Labor Amt \$92.50
Notes Authorized 0.5 to replace one slide fascia.		

Labor

Line# 2	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-12-19 11:12:12 :: BATHROOM CABINET DOORS RUB Doors are rubbing. Moved doors over with a hammer. Doors are now clearing each other.		
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$18.50
Serial#	Appr Hrs 0.10	Appr Labor Amt \$18.50
Notes		

Submitted	Labor Amt	\$203.50	Approved	Labor Amt	\$111.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$203.50		Total	\$111.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____

DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.