



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78737
Promised Date: 31 DEC 25



CUSTOMER WORK ORDER

WO #: 78737
Customer: 45335 - WINGO, JOSEPH -
812-673-2364
Tag:
Author: PH
Location: 0109 CHECK PREAUTH

Stock #: 11494
Stock Desc: 2025 TT COACHMEN
FREEDOM EXPRESS 29SE
Chassis #: 5ZT2FEUB3SW030317
Serial #: 5ZT2FEUB3SW030317
Mileage: 0
Licence:

Invoice #:
Date In: 29 DEC 25
Promised: 31 DEC 25
Date Sched:
Completed: 31 DEC 25
Warr. Date: 31 DEC 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery and air pressure correct in all 5 tires. Exterior inspection looks good Awning fabric and hardware looks and works properly Awning lights work properly. Roof inspection found a couple voids that I filled with dicor self-leveling roof good now. Interior inspection hooked up to city water and flushed out all the lines. Put water in fresh tank and ran water pump and it worked properly. Stove works properly microwave works properly refrigerator works properly microwave works properly both ac units works properly furnace works properly water heater works properly tv antenna works properly now after i installed a new antenna. Everything else lookes good and works properly

Customer #: 45335
WINGO, JOSEPH



Labor Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1200 - Internal

COMPLAINT: INSTALL EQUALIZER 1200 WEIGHT DISTRIBUTION HITCH

CAUSE: Install hitch work
New hitchwork installation

CORRECTION: Installed hitch brakets to camper and put the rest of the hitch in side compartment. Had to move spare tire back a little so it would give. Clearance for the hitch brakets. Leveled the camper then checked the ball height and matched the truck hitch. Connected the camper to truck and adjusted as needed. Connected the 7-way plug, safety chains, breakaway cable. Drove the vehicle out the gate.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C



Z990 MISC LABOUR CODE (EXTERNAL) SAR N/C

Parts				
Part #	Description	Qty	Price	Total
14-2928	12,000LB. EQUALIZER ADJ HITCH	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1200: 0.00

Job #DELUXE - Internal
DELUXE STARTER KIT

Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.
 INCLUDES 2 GALLONS OF ANTI-FREEZE
 UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA
 DE-WINTERIZATION IS NOT INCLUDED
 NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Found water pump and turned it to winterize mode. Ran winterize solution through the water pump to kitchen faucet hot and cold until solution was there. Repeated on bathroom sink faucet bathroom shower and toilet. Used 2 gallons of winterize solution. Drained black tank and gray tanks and fresh tank. Good to go

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C
Z990	WINTERIZE UNIT	JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: TOILET WILL NOT HOLD WATER

CAUSE: Toilet won't hold water

CORRECTION: After inspection of the toilet i found that the ball valve was not touching the rubber gasket and the water was just going straight out. So i thought it was the gasket so when i was getting ready to replace the gasket i found that it wasn't snapped in the toilet. So once i snapped it in its location the ball valve touched the bottom of the gasket and the toilet holds water like its supposed to do. Toilet good to go now

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	46.25

W/O: 78737
Promised Date: 31 DEC 25



Customer #: 45335
WINGO, JOSEPH



Subtotal for Job #1:

46.25

Job #2 - Warranty

COMPLAINT: NO TV RECEPTION

CAUSE: Tv antenna not getting signal

CORRECTION:

After inspection of the TV and antenna, I found it wasn't getting a signal. Took the booster out of the wall, traced down all of the cables to their locations, made sure that there was a signal through all of the cable connections that was good, but still wasn't getting a signal. Pull the unit outside, test the system again. Still no sign. Took the booster out of the wall, traced down all of the cables to their locations, made sure that there was a signal through all of the cable connections that was good, but still wasn't getting a signal. Pull the unit outside and test the system again. Still, no signal change in the booster plate. Still no signal. Took the antenna off the roof. Put it outside, still no signal, got a tester antenna, hooked it up, put it outside, got signal, brought it back inside, hooked it up to the cable coming through the roof. We had a signal. Put in a parts request for a new antenna. Got the part tested it first. Got the part tested it first. It worked properly. Then I put beetle tape on the bottom of it, secured to the roof. Sealed it with Dicor self-leveling. Then I started putting all of the things back together. When I started doing that, I noticed that all of the factory cable connectors were not properly. Installed, I put 4 new cable ends on and hooked them up. Everything is up, got it. Everything is up, got it all back secured. In the wall. Everything is up, got it all back secured. On the wall, we tested a TV, the main TV that comes with the camper, and our test TV in the back bedroom; everything worked properly. Cleaned up my mess. An antenna is good to go

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	281.20
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	366.30

Parts Part #	Description	Qty	Price	Total
020041	AR2-5G1 AIR 360+ 5G ANTENNA	1.00	213.12	213.12
Subtotal for Job #2:				860.62

Job #3 - Warranty

COMPLAINT: CITY INLET CHECK VALVE IS LEAKING

CAUSE: City water inlet leaks

CORRECTION: During winterize the city water inlet check vale started leaking

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts Part #	Description	Qty	Price	Total
94234	FLUSHER WATER FLANGE W/BRASS VALVE, WHT	1.00	20.27	20.27
Subtotal for Job #3:				75.77

Job #WALK - Internal

COMPLAINT: WALK THRU

CAUSE: Showing the customers the inside and out of the camper

CORRECTION: Showing the customers the inside and out of the camper

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

W/O: 78737
Promised Date: 31 DEC 25



Customer #: 45335
WINGO, JOSEPH



Subtotal for Job #WALK: 0.00

Parts Total: 233.39
Labour Total: 749.25
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 982.64

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 06 Jan 2026

Customer Signature : _____

W/O: 78737
Promised Date: 31 DEC 25



Customer #: 45335
WINGO, JOSEPH

