

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78738
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 19476 - DAVID WELLS
Address: 9120 OLD HWY 62 E
MT VERNON, IN
47620

Phone:

Stock Number: 2025 CAMPSITE DELUXE CAMPSITE

VIN:

HIN:

SER#: 5ZT2CRRB2SZ080648

Mileage:

Work Order Comp: 09 JAN 26

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 29 DEC 25

Inv #: 425774

WO # Job # Description JOB INFORMATION

78738 2 CUSTOMER RAN ROOM IN AND THE REAR OF THE ROOM DID NOT COME ALL THE WAY IN. THIS IS THE PROBLEM HE WAS HAVING BEFORE HIS LAST VISIT HERE, HOWEVER, ON THE LAST VISIT, HE WAS HAVING TROUBLE WITH THE FRONT SIDE OF THE ROOM.
Slideroom motor assembly on the rear
Ran the slideroom out and the slideroom was popping ran the slideroom back in. Put in a parts request for a new slideroom motor.

78738 3 CUSTOMER ADVISES THAT THE FURNACE IS NOT PUTTING OUT ANY AIR IN THE BATHROOM.
Damage furnace vent and not connected properly
Went to the thermostat to turn on the furnace and then checked the airflow in the bathroom. Did not feel any heat or air flow coming out of the vent in the bathroom. UnscrewThe vent that is next to the shower pan, to check to make sure it was connected. The furnace vent was partially connected and then checked under the shower pan to see if it was connected there. Took pictures of the furnace vent connected but damaged. Unscrew the cabinet from the wall and unscrew the shower glass doors and then the shower pan to gain access to the furnace vent under the shower pan. Took more pictures of the furnace vent not being connected. The furnace vent look like it had been pulled to tight and ripped the vent hose. Spliced in new hose under the shower pan and then ran it back over towards where it comes out of the cabinet. Put the shower pan back in place and shower doors. Put the cabinet back

Claim : 78738

 WO # Job # Description JOB INFORMATION

in the corner next to the shower. Trimmed the shower doors with sealer. Turn on the furnace and check the airflow coming out of the vent in the bathroom. Vent has flow and heat but is not as strong as the bedroom or the living room.

 Part No Job# Description PARTS Qty Price Total

 720134 2 Actuator - Motor Kit - LH - 20201 1.00 233.78 233.78

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 1.00 185.00 185.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 1.00 185.00 185.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 2.00 185.00 370.00

Parts Total: 233.78
 Labour Total: 740.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 973.78

Customer Signature: _____

Date: _____