



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78820
Promised Date:
21 JAN 26

CUSTOMER WORK ORDER

WO #: 78820

Customer: 27388 - CARRICO, WILLIAM -
812-484-7785

Tag:

Author: BH

Location: 0131 DELIVERY

Stock #: 11544

Stock Desc: 2025 TT COACHMEN

FREEDOM EXPRESS 326BHDS

Chassis #: 5ZT2FEYB5SW030703

Serial #: 5ZT2FEYB5SW030703

Mileage: 0

Licence:

Invoice #:

Date In: 12 JAN 26

Promised: 31 JAN 26

Date Sched:

Completed: 28 JAN 26

Warr. Date: 16 JAN 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery. Exterior inspection looks good. Roof inspection found a couple voids in the sealer that I filled with dicor self-leveling roof good now Interior inspection. Hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly both ac units works properly furnace works properly. Water heater was not working properly so i tested the water by removing the lp line then hooking up a temporary lp tank straight to water heater and it worked properly. So then i traced the problem to bad lp gas in tanks so we burned off lp and re purged the tanks and re filled them system works properly now. Put water in fresh tank and ran water pump and it worked properly. Did my LP drop test on the outside port with stove and furnace running. Had to replace lp regulator. System work properly now. Everything else works properly. Good to go

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER - Internal

COMPLAINT: INSTALL 1400# EQUALIZER HITCH

CAUSE: Hitch work
Setup hitchwork

CORRECTION: Installed the hitch brakets on the camper and put the rest in the side compartment. Had to move Emergency barke it was in the way of the brackets.
I setup the hitchwork and adjusted as needed

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C



Customer #: 27388
CARRICO, WILLIAM

Parts

Part #	Description	Qty	Price	Total
14-2969	14,000lb EQUALIZER ADJ HI	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Found water pump and turned it to winterize mode and ran 3 gallons of winterize solution through the pump and the lines to the front bathroom sink faucet cold and hot until solution was there. Then repeated it for shower faucet toilet kitchen faucet back bathroom faucet and toilet then outside kitchen faucet and spray port. Then depressed city water inlet. Then drained blackboth black tanks and both grey tanks. And fresh tank. And turned battery disconnect off

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: REPLACE LP REGULATOR

CAUSE: Bad regulator

CORRECTION: Could not get the lp regulator to work correctly could not get it adjusted correct it was bottomed out amd it had low lp pressure. So i replaced regulator and system is working properly. Did a leak check on my connections no leaks

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50

Parts

Part #	Description	Qty	Price	Total
06-0443	MEGR-253P LP REGULATOR 2-STAGE	1.00	72.84	72.84

Subtotal for Job #1: 165.34

Job #2 - Internal

COMPLAINT: WATER HEATER NOT WORKING

CAUSE: On demand water heater not working

CORRECTION: Tested lp pressure at the water heater. It was 13 with stove and furnace running and held

W/O: 78820
Promised Date: 31 JAN 26

Customer #: 27388
CARRICO, WILLIAM


then when system was shut down. Regulated water pressure in and ran off a different lp tank. System worked properly. So we think lp tanks wasn't purged correctly.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

SPRAY PORT HOSE MISSING

Parts

Part #	Description	Qty	Price	Total
09-7146	PF26-7003 BLUE QUICK CONNECT HOSE	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total: 72.84
Labour Total: 92.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 165.34

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Jan 2026

W/O: 78820
Promised Date: 31 JAN 26



Customer #: 27388
CARRICO, WILLIAM

