



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 78828  
Promised Date:  
24 JAN 26

### CUSTOMER WORK ORDER

WO #: 78828

Customer: 3801 - FIFIELD, MICHAEL -  
270-993-3819

Tag:

Author: BJW

Location: 0209 BH TO CLOSE

Stock #: 11586

Stock Desc: 2025 DELTA 262RB

Chassis #: 7M5TD2924SC306309

Serial #: 7M5TD2924SC306309

Mileage:

Licence:

Invoice #: 426349

Date In: 15 JAN 26

Promised: 31 JAN 26

Date Sched:

Completed: 10 FEB 26

Warr. Date: 29 APR 25

#### Job #1 - External

COMPLAINT: ESTIMATE TO REPLACE EXISTING POWER FAN  
IN BATHROOM WITH A UNIT THAT HAS WALL  
REMOTE. CUSTOMER WANTS THIS IN SMOKE OR  
BLACK

CAUSE: The customer requested that we  
change out the bathroom roof vent to a  
larger fan with wall remote control

#### CORRECTION: I

started by removing the sealer around  
the roof vent and found that the sealer  
pulled off of the roof with ease. The  
sealer is still soft and sticky all over  
the roof. Leafs are sticking to the  
sealer all around the roof. I removed  
all or the screws from the bathroom roof  
vent. I removed the inner vent trim  
inside the bathroom. I unhooked the  
power from the fan. I was then able to  
remove the vent from the roof. I  
repaired the roof for the new vent. I  
installed the new vent and sealed around  
the vent. I installed the inside trim. I  
tested the vent and it is working as it  
should.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

#### Parts

Part #	Description	Qty	Price	Total
A00-07500K	MAXXFAN DELUXE ROOF VENT W/ 12V FAN	1.00	N/C	N/C

#### Other Services


Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**



Customer #: 3801  
FIFIELD, MICHAEL





**Job #2 - Warranty**

COMPLAINT: USB CHARGING PORTS ARE NOT WORKING. CUSTOMER STATES IT IS THE USB C OUTLETS NOT WORKING. CUSTOMER ADVISES THAT ALL OF THE A'S WORK, BUT ONLY 1 OF THE C'S IN ONE OF THE RECLINERS IS WORKING. ALL THE OTHER C'S ARE NOT WORKING.

CAUSE: USB charge ports on couch have been broken internally. The internal guts at the C-port charger on one of the chairs is completely gone. The other chair has a nonfunctioning C-port charging port. The A-charging ports work as they should on both. All other C-ports in camper work.

CORRECTION: I opened up the unit and plugged it into shore power. With the unit charging the battery, I tested all of the USBs and charged ports. I found that all of the charge ports are working as they should expect for the 2 C-ports on the chairs. One of the ports has missing internals. The other C-port charge port don't work at all. The buttons with the charge ports need to be replaced. If we can not get the buttons, we will need to replace the couch. I tested all the other USB's in the camper. All of the other USBs are working as they should. I recommend getting new cords if the customer is having trouble with the other charge ports. I took pictures of all the charge ports working.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	111.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	185.00

**Parts**

Part #	Description	Qty	Price	Total
2023036636	BLACK SWITCH WITH LIGHT ON/OFF W/US	2.00	38.03	76.06
2023037980	27.5" RA RECLW/SS WHITE LED/USB/CPOR	1.00	1,032.67	1,032.67
2023037981	27.5" LA RECL W/SS WHITE LED/USB/CPO	1.00	991.99	991.99
2023025690	5" CONSOLE W/STORAGE LID,2 CUPS, FIR	1.00	558.19	558.19

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-SWITCHES	1.00	10.80	10.80
FRT	FREIGHT-SOFA	1.00	128.13	128.13

**Subtotal for Job #2: 3,093.84**

**Job #3 - Warranty**

COMPLAINT: DICOR ON THE ROOF IS NOT SICKING AND ITS TACKY AND HAS LEAVE ALL OVER IT

CAUSE: Leafs are sticking to the roof sealer. The sealer is still soft and sticky. The sealer also peels off of the roof with ease. Roof membrane also has a ruff texture to it.

CORRECTION: I checked to see it this is covered by warranty.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	610.50
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	314.50

**Parts**

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



69-8349	N102101T SELF-LEVELING SEALER - ALPH	19.00	9.05	171.95
69-8347	ALPHA NON-SAG WHITE SEALER	1.00	10.21	10.21
<b>Subtotal for Job #3:</b>				<b>1,107.16</b>

Parts Total:	2,841.07
Labour Total:	1,221.00
Sublet Total:	0.00
Extras Total:	138.93
<b>WORK ORDER TOTAL:</b>	<b>4,201.00</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 10 Feb 2026

Customer Work Order

W/O: 78828  
Promised Date: 31 JAN 26



Customer #: 3801  
FIFIELD, MICHAEL

