

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78832
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11585 - 2025 CATALINA SUMMIT 231MKS 5ZT2CAMB0SU046102
VIN: 5ZT2CAMB0SU046102 HIN: SER#: 5ZT2CAMB0SU046102
Mileage: 0 Work Order Comp: 31 JAN 26
Auth. No: Dealer #:
Warr. Date: Work Order Date: 16 JAN 26 Inv #: 426299

```
*****
WO #      Job #   Description      JOB INFORMATION
*****
78832      1      LIGHT STRIP ON BOTH SIDES ARE DAMAGED AND NEEDS REPAIRED
              Both of the l.e.d. light strips are not secured to the insert
              trim. One of them has dead spots on it and will need replaced.
              Pulled the top half of the lights out and reinstalled them on
              both sides. Waiting on approval and parts for the door side
              light.

78832      2      ODS SLIDE LOWER DECAL TORN
              The decal is damaged and needs replaced.
              Used heat gun to loosen cracking and brittle decal... did not
              peel away from cabinet but worked with it till it did. Used
              mineral spirits amd rag to remove adhesive from units side wall.
              Sprayed down wall with soapy water and soap on backside and wall
              and squeezed out bubbles and air.

78832      8      MISSING LIGHT LENS IN THE BATHROOM
              Light cap is missing

78832      10     TANK FLUSH HOSE NOT INSTALLED
              Water line isnt secured to the vacuum breaker
              Installed water line.

78832      3      DOOR SIDE UPPER CORNER NEEDS FIXED
              There is a small gap where the inert trim meets the corner.
              Applied silicone to the gap.
```

Claim : 78832

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
78832      4      UNDER SLIDE ROOM RUBBER SEAL IS NOT TOGETHER AND NEEDS FIXED
                Slide seal isnt secured under the slide room.
                Took a heat gun and warmed up seal. Moved seal back behing the
                plastic trim and secured with screws.

78832      5      THE MICRWOAVE DRIP PAN IS NOT INSTALLED
                Install pan under microwave
                Removed microwave and secured the pan to the cutout. Installed
                microwave.

78832      6      THE SHOWER NEEDS SEALED
                There are gaps in the silicone.
                Applied silicone on the top of the shower surround.

78832      7      DOOR SIDE BED ROOM WALL PANEL LOOSE
                Wall panel is loose.
                Secured panel with Brad nails and filled holes with putty.

78832      9      WALL BOARD NOT ATTACHED FOOT BOARD OF BED
                Panel is loose.
                Secured panel with Brad nails and filled holes with putty.

78832     11      FRONT SLIDE ROOM TRIM NEEDS STAPLED
                Trim is loose.
                Secured trim with Brad nails and filled holes with putty.

78832     12      PAPER TOWEL HOLDER CAPS WONT STAY ON
                The caps that cover the screws are not holding.
                Applied glue to the caps and secured them to the screws.

78832     13      REAR SLIDE TRIM NEEDS STAPLED
                Trim is loose.
                Secured trim with Brad nails and filled holes with putty.

78832     14      BLIND IN SLIDE ROOM IS NOT STAYING UP
                Tension on blind needs tightened.
                Tightened the tension on the blind.

78832     15      BOTH REAR SMALL SHADES ARE NOT STAYING UP
                2blinds need tension adjusted.
                Tightened the tension on both blinds.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
F100625105      1   LIGHT, UL 108" UNDERMOUNT SMOKE 6   1.00      55.30      55.30

```

Claim : 78832

```

*****
Part No      Job#  Description      PARTS      Qty      Price      Total
*****
F100597137    2  GRAPHIC, #44 "SUMMIT SERIES" SIDE  1.00      11.95      11.95
F100330465    8  LIGHT, 4.5" MUSHROOM CEILING LIGH  1.00       2.30       2.30
10-1211       10  20183 3-PK 1" HOSE FILTERS        1.00       3.95       3.95

```

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      1  MISC LABOUR CODE (EXTERNAL)        0.40     185.00      74.00
Z990      1  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990      2  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990      2  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990      2  MISC LABOUR CODE (EXTERNAL)        0.40     185.00      74.00
Z990      2  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990      8  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990      8  MISC LABOUR CODE (EXTERNAL)        0.05     185.00       9.25
Z990      8  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990      8  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990     10  MISC LABOUR CODE (EXTERNAL)        0.00     185.00       0.00
Z990      3  MISC LABOUR CODE (EXTERNAL)        0.20     185.00      37.00
Z990      4  MISC LABOUR CODE (EXTERNAL)        0.20     185.00      37.00
Z990      5  MISC LABOUR CODE (EXTERNAL)        0.10     185.00      18.50
Z990      6  MISC LABOUR CODE (EXTERNAL)        0.10     185.00      18.50
Z990      7  MISC LABOUR CODE (EXTERNAL)        0.20     185.00      37.00
Z990      9  MISC LABOUR CODE (EXTERNAL)        0.20     185.00      37.00
Z990     11  MISC LABOUR CODE (EXTERNAL)        0.10     185.00      18.50
Z990     12  MISC LABOUR CODE (EXTERNAL)        0.10     185.00      18.50
Z990     13  MISC LABOUR CODE (EXTERNAL)        0.10     185.00      18.50
Z990     14  MISC LABOUR CODE (EXTERNAL)        0.05     185.00       9.25
Z990     15  MISC LABOUR CODE (EXTERNAL)        0.10     185.00      18.50

```

```

*****
Excode  Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT      1  UPS-LIGHT AND DECAL                1.00     16.26     16.26

```

```

Parts Total:      73.50
Labour Total:     425.50
Sublet Total:       0.00
Extras Total:      16.26

```

>>>> Claim Total: 515.26

Customer Signature: _____

Date: _____