

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2554847
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB1TU046572
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	103 / 103
Labor rate:	\$185.00	ITEM #	CAT261BH-8
OWNER INFORMATION		DEALER RO #	78834
		CLAIM START DATE	01/19/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor

Line# 1	Operation Code 30-102-24-00-001094	Operational Description Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/ Repair/No Tread Code
---------	---------------------------------------	---

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-01-19 10:07:56 :: WALL PANEL BACK WALL BUNKS ARE LOOSE Staples in wallboard pulled through behind the same tape. I carefully remove the seam tape on the back wall inside the lower bunk. I took pictures of the paneling from multiple angles. I stapled the wallboard back to the stud. I put the tape back in place and smoothed it out. I moved to the top bunk and carefully removed the seam tape. I took pictures and stapled the wallboard back to the stud. I reinstalled the seam tape and smoothed it out.

Model#	Dlr Sub Hrs	0.80	Sub Labor Amt	\$148.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$92.50

Notes

EXCESSIVE AMOUNT REQUESTED. CHANGED TO SIMILAR REPAIR TIME FOR SIMILAR REPAIRS
THE REQUESTED REPAIR CAN BE COMPLETED IN THE TIME ALLOTTED

Submitted	Labor Amt	\$148.00	Approved	Labor Amt	\$92.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$148.00		Total	\$92.50

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	