



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78836



CUSTOMER WORK ORDER

WO #: 78836

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0205 CHECK STATUS WITH
JRK

Stock #: 11597
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT 221EPIC
Chassis #: 5ZT2CALB1SU046143
Serial #: 5ZT2CALB1SU046143
Mileage: 0
Licence:

Invoice #:
Date In: 16 JAN 26
Promised:
Date Sched:
Completed: 05 FEB 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: BOTH FRONT LED LIGHTS ARE COMIN APART

CAUSE: Both lights came loose from the track.
Replace doorside Accent Light and seal at top.

CORRECTION: I was able to secure the off door side. The door side lights have a deadpot and need replaced. There's also a gap at the top that needs sealed once it dries.
Removed old accent light and replaced with new one. Sealed top with Black Dicor. Wire connections done with crimped heat shrink connectors.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	81.40
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	29.60

Parts

Part #	Description	Qty	Price	Total
F100625105	LIGHT, UL 108" UNDERMOUNT SMOKE 62 S	1.00	55.30	55.30
90M13170A	(CHEROKEE) GEOCEL 2300 BLACK SEALANT	1.00	9.76	9.76

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LIGHT KIT	1.00	16.26	16.26

Subtotal for Job #1: 192.32

Parts Total: 65.06
Labour Total: 111.00
Sublet Total: 0.00
Extras Total: 16.26
WORK ORDER TOTAL: 192.32

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer #: 1000
BASDEN'S AMERICAN RV,



Customer Signature : _____

Date: 05 Feb 2026

W/O: 78836

Customer Work Order



Customer #: 1000
BASDENS AMERICAN RV,

