



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78839
Promised Date:
24 JAN 26

CUSTOMER WORK ORDER

WO #: 78839

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 0203 BH TO CLOSE

Stock #: 11600
Stock Desc: 2025 TT KEYSTONE
COUGAR HALF-TON 25MLE
Chassis #: 4YDTCGM20SV506469
Serial #: 4YDTCGM20SV506469
Mileage: 0
Licence:

Invoice #:
Date In: 16 JAN 26
Promised: 31 JAN 26
Date Sched:
Completed: 31 JAN 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: LP COVER SCREWS FELL OUT AND MISSING THE NUTS THAT HOLD THE TOP

CAUSE: Screws missing in a top of l p cover

CORRECTION: Took old cover off, replaced it with a new cover installed. The boat Took old cover off, replaced it with a new cover installed. The boats tightened the boats up good to go.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	18.00
Z990	MISCELLANEOUS REPAIR	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
731088	LP Cover - Replacement Lid - For Dou	2.00	6.92	13.84

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LID PARTS	1.00	12.10	12.10

Subtotal for Job #1: 43.94

Job #2 - Warranty

COMPLAINT: THE BACKSPLASH OVER THE COUNTER TOP IN FRONT OF THE MAIN DOOR IS COMING OFF THE WALL

CAUSE: Backsplash coming off the wall

CORRECTION: Backsplash coming off the wall. Took the receptacle out and the light off. The backsplash was only held to the wall about 2 inches. So i sprayed adhesive on the back of the back splash and pressed it back up and put the light back up and the receptacle and put clear silicone up the edge to hold the trim on. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	36.00

Subtotal for Job #2: 36.00

Job #3 - Warranty

COMPLAINT: LED STRIP OVER THE KITCHEN AREA TOO LONG AND HANGING DOWN IN THE CORNER

CAUSE: Led strip light hanging down



Customer #: 1000
BASDENS AMERICAN RV,



CORRECTION: Put some glue on the back of the light strip to hold it up. Good to go now

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	54.00
Subtotal for Job #3:			54.00

Job #4 - Warranty

COMPLAINT: ADJUST THE ENTRY DOOR

CAUSE: Adjust entry door

CORRECTION: After inspection of the door i found that the striker needed adjustment. Once i adjusted the striker the door shuts properly. Good to go

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	54.00
Subtotal for Job #4:			54.00

Parts Total: 13.84
Labour Total: 162.00
Sublet Total: 0.00
Extras Total: 12.10
WORK ORDER TOTAL: 187.94

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Feb 2026

W/O: 78839
Promised Date: 31 JAN 26



Customer #: 1000
BASDEN'S AMERICAN RV,

