



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78847
Promised Date:
24 JAN 26

CUSTOMER WORK ORDER

WO #: 78847 (Appointment Date: 19 JAN 2026 - Time: 10:00am)

Customer: 55160 - MCCOMBS,
DARRELL - 618-201-8291

Tag:

Author: BJW

Location: 0209 CHECK STATUS WITH
CCV

Stock #: 11588

Stock Desc: 2025 5W ALLIANCE RV
AVENUE 23ML

Chassis #: 7M5FA282XSA010858

Serial #: 7M5FA282XSA010858

Mileage: 0

Licence:

Invoice #:

Date In: 19 JAN 26

Promised: 31 JAN 26

Date Sched:

Completed: 09 FEB 26

Warr. Date: 31 MAY 25

Job #1 - Internal

COMPLAINT: CUSTOMER ADVISES THAT THE TOILET IS NOT HOLDING WATER IN THE BOTTOM OF THE BOWL.

CUSTOMER ADVISES THAT UNIT IS WINTERIZED.

CAUSE: Toilet not holding water

CORRECTION: Brought unit in found line to connect antifreeze to city water to run antifreeze through system since unit is winterized. Went to toilet and ran. When flap closes toilet does not hold water. noticed toilet does not have flap seal. Parts request submitted for new ball seal. Received new seal. Placed inside toilet. Ran antifreeze and toilet held antifreeze in bowl

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
385311658	310 seal	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #COVER-L - External

COMPLAINT: Transferred to BAS*78955 on 04 FEB 26

Estimate amount was 0.00

INSTALL LARGE SLIDE COVER 138" TO 192"

CAUSE: Slidetopper

CORRECTION: Brought unit in received slidetopper. Grabbed lift went to slideroom and installed brackets. Then measured top of slideroom to 5 inches above and set putty tape on back of fabric guide. Secured into place. Set brackets in topper and ran fabric through guide. Once in place secured topper to brackets. Pulled pins on roller and ran room in and out to find true spot for fabric. Once found placed set screws in place and placed screw cover on bracket.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C



Customer #: 55160
MCCOMBS, DARRELL



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	0.00	N/C	N/C
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #COVER-L: 0.00

Job #3 - Warranty

COMPLAINT: THE DRAWER ON THE STOVE IS NOT CLOSING PROPERLY.

CAUSE: Range drawer

CORRECTION: Beought unit in. Ran slideroom out to access drawer. When removing drawer noticed right side did not want to come out. Removed drawer from guides and found the side on the drawer itself is damaged. Has large crack in wood running down side. Parts request submitted for new drawer

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
12471	CUSTOM PANTRY DRAWER - ALLIANCE	1.00	52.00	52.00

Other Services

Code	Description	Qty	Price	Total
FRT	FED-EX - DRAWER	1.00	13.05	13.05

Subtotal for Job #3: 83.55

Parts Total: 52.00
 Labour Total: 18.50
 Sublet Total: 0.00
 Extras Total: 13.05
WORK ORDER TOTAL: 83.55

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Feb 2026

