

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2558781
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZTCFLS01TP432892
USA		CHASSIS VIN	1FDWE3FN3SDD32716
		MILEAGE	7395
		SITE/WAREHOUSE	210 / 210
		ITEM #	FLC27QBF35
		DEALER RO #	78855
		CLAIM START DATE	01/22/2026
		CLAIM END DATE	01/01/1900
Labor rate:	\$185.00		
OWNER INFORMATION			
CHUBBY CHOW FACTORY LLC			
PO BOX 3641			
Evansville, IN 47735			
USA			
Retail Date of Purchase	03/05/2025	WARRANTY EXPIRATION DATE	03/05/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	RC-039-01-00-004751	25V486, 2025-389 - FUEL LINE EXTENSION - PERFORM REMEDY - Recall/Fuel System/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-01-22 09:16:58 :: RECALL 25V486 FR ID 51-1955 UNIT NEEDS RECALL ORDERED PARTS AND WILL DO ONCE PARTS SHOW			
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$185.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$185.00
	Notes			
	1) ok nw			
	this motorhome is part of Phase#2 for this recall. Dealer MUST order the part through our parts department. Dealer MUST also follow the return instructions accordingly to the recall letter.nw			

Labor

Line# 2	Operation Code	Operational Description		
	20-49-01-11-000591	LED Light Strip - Front Cap - Exterior/Front, Fiberglass Cap, Cab Over/Replace/ Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-01-22 09:17:30 :: CAP LIGHTS ARE TURNING PURPLE Purple light Took pictures of the cap lights.			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$74.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$74.00
	Notes			
	1) ok nw			

Labor

Line# 3	Operation Code	Operational Description		
	60-136-12-00-001500	Fitting - Plumbing/Fresh Water Supply/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-01-22 09:18:38 :: SHOWER IS LEAKING AT THE DIVERTER VALVE ON SHOWER FAUCET SIDE. Shower diverter Connected the hose to the city water connection then turned on the water. Turned on the shower and turned the handle to the diverter. Took a picture of the leak.Turned off the city water connection. Disconnected the plumbing from the shower and the diverter. Unscrewed the diverter then cleaned off the pipe dope and wrapped with pipe tape. Connected the diverter together and connected it to the shower faucet. Connected the plumbing to the shower faucet and diverter. Turned on the city water connection and then the shower faucet. Turned the diverter and no leaks occurred after fix. Disconnected the hose from the city water connection and drained the grey tank.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$92.50

Serial#

Appr Hrs

0.50

Appr Labor Amt \$92.50

Notes

job code corrected

Submitted

Labor Amt	\$351.50
Parts & Freight	\$0.00
Total	\$351.50

Approved

Labor Amt	\$351.50
Parts & Freight	\$0.00
Total	\$351.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.