

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 78861  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725  
Phone:  
Stock Number: 11682 - 2026 CATALINA 333DORM 5ZT2CAYB2TX036651  
VIN: 5ZT2CAYB2TX036651 HIN: SER#: 5ZT2CAYB2TX036651  
Mileage: 0 Work Order Comp: 13 FEB 26  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 20 JAN 26 Inv #: 426423

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
78861 1 ONE OF THE MAIN COLD WATER LINES IS KINKED AND NOT ALLOWING WATER  
THROUGH.  
No water pressure  
Took off panel, looked at the water lines. The main water line  
coming in was kinked, so I cut the kink out the kink and  
installed a 90 in the line and crimped the 2 connections. The  
lines tested the water pressure back to full pressure.No leaks  
  
78861 7 UNIT HAS NO ACCESS PANEL UNDER BATHROOM COUNTER  
Acess pannel missing  
Had to order part  
  
78861 2 THE DOOR TRACK BETWEEN THE BEDROOM AND THE BATHROOM IS PULLING  
OUT OF THE CEILING.  
Bedroom door track loose at the ceiling  
Took the stripped out screw out and put in in a different place.  
And added a screw. Good now  
  
78861 3 THE DOOR SIDE NOSE CAP LIGHT IS OUT OF THE TRACK.  
Door side cap light out of track  
Made sure there wasn't any debris in the track and then gently  
pushed the ligh back in the track  
  
78861 4 BOTH ENTRY DOOR ARE IN NEED IF ADJUSTMENT AS THEY ARE BOTH HARD  
TO CLOSE.  
Both entry doors needs adjusted

Claim : 78861

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*

Adjusted the strikers and the hinges on both doors. They work properly now

78861      5      THE OUTDOOR REFRIGERATOR IS NOT CLOSING PROPERLY  
 Outdoor fridge door won't shut good  
 Pulled the refrigerator found that there was a bolt missing on the hinge. So i got a new bolt and shimmed up the door it shuts properly now

78861      6      BACK SPLASH BEHIND STOVE IS COMING OFF  
 Backsplash coming off  
 Sprayed some adhesive on the back of the backsplash and pushed it up against the wall and its all good now

\*\*\*\*\*  
 Part No      Job#      Description      PARTS      Qty      Price      Total  
 \*\*\*\*\*  
 314605      1      1/2" PEX PLASTIC 90 DEGREE ELBOW      1.00      0.33      0.33  
 7815      7      PANELING, HDF 2.7 MM X 4' X 8' CH      1.00      46.18      46.18

\*\*\*\*\*  
 Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total  
 \*\*\*\*\*  
 Z990      1      MISC LABOUR CODE (EXTERNAL)      0.20      185.00      37.00  
 Z990      7      MISC LABOUR CODE (EXTERNAL)      0.40      185.00      74.00  
 Z990      7      MISC LABOUR CODE (EXTERNAL)      0.00      185.00      0.00  
 Z990      2      MISC LABOUR CODE (EXTERNAL)      0.30      185.00      55.50  
 Z990      3      MISC LABOUR CODE (EXTERNAL)      0.20      185.00      37.00  
 Z990      4      MISC LABOUR CODE (EXTERNAL)      0.60      185.00      111.00  
 Z990      5      MISC LABOUR CODE (EXTERNAL)      0.25      185.00      46.25  
 Z990      6      MISC LABOUR CODE (EXTERNAL)      0.15      185.00      27.75

\*\*\*\*\*  
 Excode      Job#      Description      EXTRAS      Qty      Price      Total  
 \*\*\*\*\*  
 FRT      7      UPS FREIGHT - PANELING      1.00      149.31      149.31

Parts Total:      46.51  
 Labour Total:      388.50  
 Sublet Total:      0.00  
 Extras Total:      149.31

>>>> Claim Total:      584.32

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_