

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78868
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 2605R - 2026 FREELANDER 27QB 1FDWE3FN7SDD30130

VIN: 1FDWE3FN7SDD30130 HIN: SER#: 1FDWE3FN7SDD30130

Mileage: 2879 Work Order Comp: 18 FEB 26

Auth. No: Dealer #:

Warr. Date: Work Order Date: 20 JAN 26 Inv #: 426576

WO #	Job #	Description	JOB INFORMATION
78868	1	RECALL 25V486 FR # 51-1955 Recall Brought unit in. Disconnected plug and ran unit until stalls as recall called for. Parts request submitted for part kit	
78868	2	CAP LIGHTS ARE TURNING PURPLE Cap lights Brought unit in and turned on cap lights. Saw cap lights on unit are starting to turn purple. Parts request submitted for new cap lights	
78868	4	LP PRESSURE TEST Lp test Brought unit in connected to outside port for lp line. Starting pressure is 13iwc. Ran furnace and range for 50% load test pressure dropped to 7.5. Regulator bottomed out when trying to adjust flow parts request submitted for new regulator. Recieved new regulator. Removed old regulator from lp line then from tank. Took to vice and removed adapter from regulator. Put thread sealant on adapter and placed in new regulator. Took back to unit and attached to lp line after putting lp thread tape on line. Then attached regulator to tank and tightened down. Checked for leaks are none found so ran new lp drop test. Starting pressure was at 12iwc. At 50% load with range and furnace pressure is at 10. Adjusted to 11. Lock up pressure is 13iwc. Ran leak test at 8iwc for 5mins. Unit passed leak test.	

Claim : 78868

WO # Job # Description JOB INFORMATION

78868 3 EMERGENCY EXIT WINDOW BEHIND SOFA KEEPS COMING UNLOCKED ON
FRONT RED LATCH. I TRIED ANOTHER LATCH AND STILL DOES IT.
Window latch
Brought unit in. Went to loose window latch for emergency window.
Loosened nuts on back side and loosed bolts. Pulled latch up as
high as possible and tightened bolt and nuts back down. Used
latch. Latch holds better.

Part No Job# Description PARTS Qty Price Total

F100231286 1 32" FUEL LINE RECALL KIT 1.00 40.95 40.95
F100584060 2 BADGE, KIT BACKLIT LENS RH/LH 2-L 1.00 109.10 109.10
06-0450 4 MEGR-298P REGULATOR 1.00 56.41 56.41

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.25 185.00 46.25
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.25 185.00 46.25
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 185.00 92.50
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
Z990 4 MISC LABOUR CODE (EXTERNAL) 0.50 185.00 92.50
Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
Z990 3 MISC LABOUR CODE (EXTERNAL) 0.30 185.00 55.50
Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00

Excode Job# Description EXTRAS Qty Price Total

FRT 1 UPS-F.R. PARTS 1.00 16.28 16.28
SS 4 SHOP SUPPLIES 1.00 0.00 0.00

Parts Total: 206.46
Labour Total: 370.00
Sublet Total: 0.00
Extras Total: 16.28

>>>> Claim Total: 592.74

Customer Signature: _____

Date: _____