

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2559676
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZTCFLS03TP432862
USA		CHASSIS VIN	1FDWE3FN7SDD30130
		MILEAGE	2879
		SITE/WAREHOUSE	210 / 210
		ITEM #	FLC27QBF35
		DEALER RO #	78868
		CLAIM START DATE	01/22/2026
		CLAIM END DATE	01/01/1900
Labor rate:	\$185.00		
OWNER INFORMATION			
CHUBBY CHOW FACTORY LLC FACTORY LLC			
PO BOX 3641			
Evansville, IN 47715			
USA			
Retail Date of Purchase	05/07/2025	WARRANTY EXPIRATION DATE	05/07/2026

Claim Line Details

Labor

Line# 1	Operation Code RC-039-01-00-004751	Operational Description 25V486, 2025-389 - FUEL LINE EXTENSION - PERFORM REMEDY - Recall/Fuel System/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-22 16:01:34 :: RECALL 25V486 FR # 51-1955 Recall Brought unit in. Disconnected plug and ran unit until stalls as recall called for. Parts request submitted for part kit	
Model#	Dlr Sub Hrs 1.00	Sub Labor Amt \$185.00
Serial#	Appr Hrs 1.00	Appr Labor Amt \$185.00
	Notes 1) ok nw This motorhome is part of phase#2 for this recall. Dealer MUST order part through our parts department. Dealer MUST also follow the return instructions accordingly to the recall letter	

Labor

Line# 2	Operation Code 20-49-01-11-000591	Operational Description LED Light Strip - Front Cap - Exterior/Front, Fiberglass Cap, Cab Over/Replace/ Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-22 16:02:00 :: CAP LIGHTS ARE TURNING PURPLE Cap lights Brought unit in and turned on cap lights. Saw cap lights on unit are starting to turn purple. Parts request submitted for new cap lights	
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$37.00
	Notes	

Labor

Line# 3	Operation Code 20-46-24-00-000721	Operational Description Window - Exterior/Windows/Repair/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-22 16:02:56 :: EMERGENCY EXIT WINDOW BEHIND SOFA KEEPS COMING UNLOCKED ON FRONT RED LATCH. I TRIED ANOTHER LATCH AND STILL DOES IT. Window latch Brought unit in. Went to loose window latch for emergency window. Loosened nuts on back side and loosed bolts. Pulled latch up as high as possible and tightened bolt and nuts back down. Used latch. Latch holds better.	
Model#	Dlr Sub Hrs 0.30	Sub Labor Amt \$55.50
Serial#	Appr Hrs 0.30	Appr Labor Amt \$55.50
	Notes 1) ok nw	

Labor
Line# 4

Operation Code
50-134-01-00-001443

Operational Description
LP Regulator - Includes Leak Test - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-01-22 16:09:17 :: LP PRESSURE TEST Lp test Brought unit in connected to outside port for lp line. Starting pressure is 13iwc. Ran furnance and range for 50% load test pressure dropped to 7.5. Regulator bottomed out when trying to adjust flow parts request submitted for new regulator. Recieved new regulator. Removed old regulator from lp line then from tank. Took to vice and removed adapter from regulator. Put thread sealant on adapter and placed in new regulator. Took back to unit and attached to lp line after putting lp thread tape on line. Then attached regulator to tank and tightened down. Checked for leaks are none found so ran new lp drop test. Starting pressure was at 12iwc. At 50% load with range and furnace pressure is at 10. Adjusted to 11. Lock up pressure is 13iwc. Ran leak test at 8iwc for 5mins. Unit passed leak test.

Model#Dlr Sub Hrs0.50Sub Labor Amt \$92.50

Serial#Appr Hrs0.50Appr Labor Amt \$92.50

Notes

Submitted	Labor Amt	\$370.00	Approved	Labor Amt	\$370.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$370.00		Total	\$370.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.