

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS	Authorized
BARDEN RV CENTER INC		CLAIM	2562580
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB7SU045649
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	103 / 103
		ITEM #	CAT261BH-8
		DEALER RO #	78886
		CLAIM START DATE	01/27/2026
		CLAIM END DATE	01/01/1900
Labor rate: \$185.00			
OWNER INFORMATION			
CHUBBY CHOW FACOTRY LLC			
PO BOX 3641			
Evansville, IN 47735			
USA			
Retail Date of Purchase 03/27/2025		WARRANTY EXPIRATION DATE 03/27/2026	

Claim Line Details

Labor

Line# 1

Operation Code
20-43-24-00-000589

Operational Description
Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Repair/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-01-27 11:24:15 :: BUBBLE IN DECALS - ALL OVER Decal bubbles Brought unit in. Saw multiple decals had large bubbles all over unit. Went around and relaxed as many decals in bubbles as possible. Made tiny incision and removed air from bubble. Relaxed all possible bubbles. Pictures taken

Model#

Dlr Sub Hrs 0.45

Sub Labor Amt \$83.25

Serial#

Appr Hrs 0.45

Appr Labor Amt \$83.25

Notes
AUTHORIZED AS REQUESTED

Labor

Line# 2

Operation Code
20-49-01-11-000591

Operational Description
LED Light Strip - Front Cap - Exterior/Front, Fiberglass Cap, Cab Over/Replace/ Electrical

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-01-27 11:26:11 :: FRONT MOLDING LIGHTS HAVE LED BULBS OUT ON BOTH STRIPS. Led strip Brought unit in and saw both led strips had lights out on both sides. Parts request for led strips.

Model#

Dlr Sub Hrs 0.60

Sub Labor Amt \$111.00

Serial#

Appr Hrs 0.60

Appr Labor Amt \$111.00

Notes
AUTHORIZED AS REQUESTED

Labor

Line# 3

Operation Code
20-69-02-17-000708

Operational Description
Compartment Door Lock or Slam Latch - Exterior/Compartment Doors/Adjust/ Latch

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-01-27 11:27:09 :: LOCK ON ODS FRONT COMPARTMENT HAS COME APART Door lock Brought unit in. Saw lock on non door side compartment had fallen apart. Removed nut holding lock in place. Removed lock. Placed new lock in and turned nut on to tighten down lock. Placed fin on back and tested lock. Lock keeps door locked and fits in place.

Model#

Dlr Sub Hrs 0.20

Sub Labor Amt \$37.00

Serial#

Appr Hrs 0.20

Appr Labor Amt \$37.00

Notes

Submitted

Labor Amt	\$231.25
Parts & Freight	\$0.00
Total	\$231.25

Approved

Labor Amt	\$231.25
Parts & Freight	\$0.00
Total	\$231.25

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.