

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2565317
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB5SU045648
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT261BH-8
CHUBBY CHOW` LLC		DEALER RO #	78889
PO BOX 3641		CLAIM START DATE	01/29/2026
Evansville, IN 47735		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/19/2025	WARRANTY EXPIRATION DATE	04/19/2026

Claim Line Details

Labor

Line# 1	Operation Code 20-49-01-11-000591	Operational Description LED Light Strip - Front Cap - Exterior/Front, Fiberglass Cap, Cab Over/Replace/ Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-29 13:03:43 :: LED LIGHT AR OUT ON BOTH FRONT MOLDING STRIPS Led lights Brought unit in. Turned on front cap lights and saw multiple lights out on both led strips. Parts request submitted for led strips	
Model#	Dlr Sub Hrs	0.60
	Sub Labor Amt	\$111.00
Serial#	Appr Hrs	0.60
	Appr Labor Amt	\$111.00
	Notes AUTHORIZED AS REQUESTED	

Labor

Line# 2	Operation Code 20-43-24-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Repair/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-29 13:04:22 :: DECALS ARE BUBBLING ALL OVER Decals Brought unit in. Had multiple bubbles in each decal between 10-20 bubbles per. Went to each decal and made small incision to release bubble and relax decal as much as possible. Pictures taken of before and after.	
Model#	Dlr Sub Hrs	0.50
	Sub Labor Amt	\$92.50
Serial#	Appr Hrs	0.50
	Appr Labor Amt	\$92.50
	Notes AUTHORIZED AS REQUESTED	

Labor

Line# 3	Operation Code 40-196-01-11-004472	Operational Description Charging Center - USB and USB-C - Electrical/12 Volt Interior/Replace/Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-01-29 13:04:53 :: USB IN BUNK IS LOOSE Usb port Brought unit in. Saw usb port in bunk house had come loose. Removed screws from port and lined up to use nee holes. Screwed port back in and hid old holes. Port is now tight and flush with wall	
Model#	Dlr Sub Hrs	0.20
	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20
	Appr Labor Amt	\$37.00
	Notes	

Labor

Line# 5	Operation Code 30-101-01-00-001076	Operational Description Hinged Passage Door - Interior/Interior Doors/Replace/No Tread Code
---------	---------------------------------------	--

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-01-29 13:22:16 :: BATH DOOR KNOB HAS COME LOOSE
AMD RUBBED VENEER OFF Bathroom door Brought unit in. Went to bathroom door and saw veener has been
torn off of door around door knob. Also had been torn off on inside of door rubbing against door frame. Parts
request submitted for new door

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$92.50
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$92.50

Notes
REQUIRES PHOTOS
photos added
AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$333.00	Approved	Labor Amt	\$333.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$333.00		Total	\$333.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.