



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78909
Promised Date:
28 FEB 26

CUSTOMER WORK ORDER

WO #: 78909

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0213 CHECK STATUS WITH
JTW

Stock #: 11685
Stock Desc: 2026 TT KEYSTONE
SPRINGDALE 1230BB
Chassis #: 4YDTSGE13TW101761
Serial #: 4YDTSGE13TW101761
Mileage: 0
Licence:

Invoice #:
Date In: 29 JAN 26
Promised: 28 FEB 26
Date Sched:
Completed: 13 FEB 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi unit

CORRECTION: Got a battery box and installed on the tongue. Had to purge the single 20lb lp tank then fill. Mounted the lp tank. Unbolted the spare to get out the battery cables that was pinched. Put in a test battery and connected it to the camper. Checked the lug nuts to 110ftlbs and tires to 75psi. Tested the running lights, breakaway switch and brakes. Plugged in the shore cord from the camper. Connected the manometer to the lp quick connection and found the handle missing. Did an lp drop test with the furnace and water heater and stove after. Lp regulator wouldn't go above 10 wc told pete, he said to wait and check other camper like it. Made sure there was hot water at each faucet but nothing came out. Turned on the ac to cool then shut off. Used the test tv to check tv signal. Checked the roof membrane and sealer. Tested the 120v outlets, 12v items and usb ports. Tested the lp detector and smoke alarm. Checked converter output. Found a few items broke, bent or missing. Tested the microwave and fridge. Blue film stuck between the fridge and cabinet. Found the entry door difficult to shut. The vent in the bathroom has a crack in the trim.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterizing 2 gallons of antifreeze

CORRECTION: Connected the sewer hose and drained the black and grey tanks. Turned the valve at the water pump and added 2 gallons through the kitchen faucet, toilet, shower. Depressed city water



Customer #: 1000
BASDEN'S AMERICAN RV,



connection and the water heater.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: MISSING HANDLE TO LP QUICK CONNECT

CAUSE: Missing handle
Broken quick connect

CORRECTION: Took picture and put in parts request for a new lp quick connection.
Made sure lp was off and took broken quick connect off and put new thread dope on and installed new quick connect. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	0.00
Z990	MISCELLANEOUS REPAIR	SAR	18.00

Parts

Part #	Description	Qty	Price	Total
390261	Fitting - LP - Quick Disconnect Coup	1.00	25.52	25.52

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JOBS 1,2	1.00	12.14	12.14

Subtotal for Job #1: 55.66

Job #2 - Warranty

COMPLAINT: CRACK IN BATHROOM VENT TRIM

CAUSE: Crack

CORRECTION: Took picture and put in parts request for a new plastic trim.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	18.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
398049	Vent - Garnish - 5 1/4" - White	1.00	5.16	5.16

Subtotal for Job #2: 23.16

Job #3 - Warranty

COMPLAINT: BLUE FILM IS STUCK BETWEEN THE FRIDGE AND COUNTER

CAUSE: Blue film tape

CORRECTION: Took pictures. Unscrewed the fridge at the top. Once the fridge was away from the cabinet then could pull off the blue film tape. Screwed the top of the fridge back to the top of the cabinet.

Labor



Code Description
Z990 MISCELLANEOUS REPAIR

Mechanic Total
SAR 36.00

Subtotal for Job #3: 36.00

Job #4 - Warranty

COMPLAINT: ENTRY DOOR HARD TO SHUT

CAUSE: Bottom of the door

CORRECTION: Opened the door then set against the door frame to show the difference. Made sure the screws were tight on the entry door handle. Stuck a 2x6 in the door and pushed against the door to keep the bottom from hitting first and the same as the top.

Labor

Code Description
Z990 MISCELLANEOUS REPAIR

Mechanic Total
SAR 36.00

Subtotal for Job #4: 36.00

Parts Total: 30.68
Labour Total: 108.00
Sublet Total: 0.00
Extras Total: 12.14
WORK ORDER TOTAL: 150.82

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature _____

Date: 13 Feb 2026

W/O: 78909
Promised Date: 28 FEB 26



Customer #: 1000
BASDEN'S AMERICAN RV,

