



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78932
Promised Date:
26 FEB 26

CUSTOMER WORK ORDER

WO #: 78932

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0213 CHECK STATUS WITH
JRK

Stock #: 11688
Stock Desc: 2026 TT COACHMEN APEX
216RKS
Chassis #: 5ZT2CXLB3TL019584
Serial #: 5ZT2CXLB3TL019584
Mileage: 0
Licence:

Invoice #:
Date In: 30 JAN 26
Promised: 28 FEB 26
Date Sched:
Completed: 12 FEB 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Removed LP cover and disconnected Tanks, Purged and filled. Hooked up test box and outside battery power. Checked Coupling, lights, breakaway switch and brakes. Checked and adjusted Tire pressure and lug Torque. Checked all cap seals. Checked roof, found voids and informed Ben and had a Job added to fill voids. Found scuff on Large skylight and informed Ben and was advised to see if i can get it to remove!? Removed test box and hooked up shore power. Tested stability jacks. Opened all outside compartments and checked latches, seals and locks. Removed Grille shelf, Grille and Cast Iron top from compartment and opened from packing. Grille shelf has scratch/scuffs that wont remove... took pics and informed Ben, added job line and submitted part request. Opened unit up and tested Awning and light. Tested and opened up slideroom. Turned Fridge on to test later. Made sure all valves under unit was closed and located pump and positioned valves to regular use and filled Fresh Tank. Removed all Antifreeze from Water lines... outside Shower Hot side has no pressure, ALL other sides do. Hooked up Manometer and ran DropTest with Furnace and Water Heater. While running hot water, the water pressure kept sputtering as if it was struggling for flow or sucking air in the line somewhere... checked water pump and its not shutting off as if its not pressurized which leads me to believe there is a leak or air being pulled into the outlet side of pump/water lines. Looked at my water level in fresh tank and it was at 2/3 now it is Empty so i think i initially got a false read in the fresh tank (i did pull it in from outside where its freezing so that may be cause) adding more water to fresh tank. With hose on wnd running it read FULL but when i shut the water off it showed 2/3 so the Water coming from hose was engaging the Full Tank sensor. Pump primes and shuts off properly and Hot side of fixtures are working properly. Finished Droptest and LP is working properly. Turned LP back on and tested Stovetop and Grille. Turned Furnace back on to heat up inside to test ACs after lunch. Fridge and Freezer are cooling properly. Unpackaged all the other appliances removed from unit. Tested all recepticals and USB Ports. Tested Microwave. Tested Radio speaker and Bluetooth. Tested all rooftop vents. Hooked up City water connection to fill and activate Tank Sensors. Tested all blinds and windows operations. Tested TV and Antenna. Ran water from fresh tank to the Black Tank and then Bathsink and water ran out of fresh tank and i used my home to run water down the Kitchen Sink to Galley... ran liquid in all 3 tanks till sensor activated. Took pics and filled put manufacturer S/N. Dumped Tanks.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,





Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Winterized unit and filled out checksheet. 2gl used.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: ROOF NEEDS RESEALED

CAUSE: Fill voids on rooftop.

CORRECTION: Brushed out and filled voids with self leveling dicor white. And took pics.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	8.72	8.72

Subtotal for Job #1: 45.72

Job #2 - Warranty

COMPLAINT: BIG SKYLIGHT HAS A SCRATCH ON IT

CAUSE: NO ISSUES



Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE OUTSIDE GRILL SHELF IS SCRATCHED AND DAMAGED

CAUSE: Scratched up grille shelf

CORRECTION: Pulled Grille shelf out of compartment and it had scratches on on. Submitted part request. Received new grill top shelf and retrieved old one from unit. Removed the Mount Arms and transferred them to new shelf and returned it to the unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00

Parts

Part #	Description	Qty	Price	Total
F100745741	C-TOP, GRIDDLE 22"X11.5" STEEL BLAC	1.00	50.56	50.56

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-GRIDDLE TOP	1.00	16.30	16.30

Subtotal for Job #3: 103.86

Customer Order

Parts Total: 59.28
Labour Total: 74.00
Sublet Total: 0.00
Extras Total: 16.30
WORK ORDER TOTAL: 149.58

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Feb 2026

W/O: 78932
Promised Date: 28 FEB 26



Customer #: 1000
BASDEN'S AMERICAN RV,

