

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA  <b>Labor rate:</b> \$185.00 <b>OWNER INFORMATION</b>	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 2572443 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2CAUB7TN302635 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 300 / 300 <b>ITEM #</b> CAT293QBCKLE-300 <b>DEALER RO #</b> 78933 <b>CLAIM START DATE</b> 02/05/2026 <b>CLAIM END DATE</b> 01/01/1900
--	--

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	<b>Operational Description</b>		
30-307-01-00-003674	Fireplace Front Glass Only - Interior/Fireplace/Replace/No Tread Code		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2026-02-05 16:10:01 :: SCRATCH ON FIRE PLACE GLASS Fireplace glass During pdi noticed a chip in the fire place glass. Parts request submitted			
<b>Model#</b> WD914-30CT	<b>Dlr Sub Hrs</b> 0.20	<b>Sub Labor Amt</b> \$37.00	
<b>Serial#</b> 100000008000	<b>Appr Hrs</b> 0.20	<b>Appr Labor Amt</b> \$37.00	
<b>Notes</b>			
AUTHORIZED AS REQUESTED			

### Labor

**Line# 2**

<b>Operation Code</b>	<b>Operational Description</b>		
30-100-02-00-001044	Drawer Guides or Tracks, pair - Interior/Cabinetry/Adjust/No Tread Code		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2026-02-05 16:10:37 :: BUNK ROOM DRAWER WONT CLOSE Drawer not closing During pdi noticed the drawer under the bunkroom couch would not close. Removed drawer from guides. Once removed saw the screw had come out on the guide and on the rail for drawer itself. Placed screw back into both. Once tightend and fixed tried to put drawer back on but noticed the guide it was not straight and would not line up with drawer to connect. Removed screw holding in place and added washers behindmto push out and straighten up. After that placed drawer back in. Drawer connects to guide and opens ans closes properly			
<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.20	<b>Sub Labor Amt</b> \$37.00	
<b>Serial#</b>	<b>Appr Hrs</b> 0.20	<b>Appr Labor Amt</b> \$37.00	
<b>Notes</b>			

### Labor

**Line# 3**

<b>Operation Code</b>	<b>Operational Description</b>		
30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2026-02-05 16:12:53 :: BAHTRROOM DOOR TRIM CUT SHORT Door trim During pdi noticed bathroom door trim was cut short leaving a gap on both sides to see through to the wood of wall. Parts request submitted for new door trim			
<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.40	<b>Sub Labor Amt</b> \$74.00	
<b>Serial#</b>	<b>Appr Hrs</b> 0.40	<b>Appr Labor Amt</b> \$74.00	
<b>Notes</b>			
AUTHORIZED AS REQUESTED			

### Labor

**Line# 4**

<b>Operation Code</b>	<b>Operational Description</b>		
30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/		

