

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78937
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11694 - 2026 APEX NANO 208BHS 5ZT2CXKB6TA000279

VIN: 5ZT2CXKB6TA000279 HIN:

SER#: 5ZT2CXKB6TA000279

Mileage: 0

Work Order Comp: 19 FEB 26

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 30 JAN 26

Inv #: 426611

WO # Job # Description JOB INFORMATION

78937	2	ENTRY STEPS NEED ADJUSTED Step door frame brackets would not allow the staircase to fold down. The right hand side of the step was stuck on the door hinge. I unbolted the brackets and adjusted them as needed to work with the door frame. I tested the fold up and down 3 times. The steps are now folding up and down as the should.
78937	1	KITCHEN MINI BLINDS MISSING WALL ANCHORS AND ADJUSTMENT ROD The kitchen mini blind is missing the adjustment rod and lower wall anchors. I put in a parts request for get the mini blind wall anchors and adjustment rob. I received the adjustment rod and installed it in the unit.
78937	3	12 INCH ROOF VENT FAN SHROUD ISN'T FLUSH WITH CEILING Wiring over fan shroud prevented fan shroud from going into the ceiling all the way. I removed the fan shroud and tucked the wiring into the open area inside the fan housing. I was then able to reinstall the fan shroud. Now the fan shroud fits flush with the ceiling.
78937	4	SLIDE ROOM MAKING POPPING NOISE WHEN GOING IN AND OUT The slide room popped when it would start to go out. Sealer on the bulb seal was sticking to the T-molding. I found screws under the slide room when I ran it out. I did not

Claim : 78937

 WO # Job # Description JOB INFORMATION

hear the slide room pop again until I closed the room again.
 After I let the room sit for an hour, it did popped again when I
 ran it back out. I found the the sealer over the bulb seal was
 sticking to the T-molding on the outside of the unit. I sprayed
 the bulb seal with a silicone spray to keep it from sticking
 again.

78937 5 BREAKAWAY SWITCH IS BROKEN
 The brake-a-way switch mount is damaged and the switch needs
 replaced.
 I removed the bad brake-a-way switch from the front of the unit.
 I installed a new brake-a-way switch on the front of the unit and
 wired it to the unit. I tested the switch and it is working as it
 should.

78937 6 FIX OUTSIDE KITCHEN WALL BOARD
 Interior wall board in outside kitchen is loose under the door.
 I glued the wall board in place and clamped it. This will hold
 the small peace of wall board.

78937 7 FIND OUT WHY THE USBC IS NOT WORKING WITH ALL CORDS
 All C-port USB in the unit do not work with a standard charge
 cord. They only work with a high speed data cable.
 I tested all of the USB ports in the camper and found that my USB
 testing tool worked on all of the A-port USBs. It did not work on
 any of the C-ports. I tried plugging in a cell phone to the USB
 testing tool and checking the C-ports. I could not get anything
 out of the C-port at all. I borrowed a high speed data cable from
 one of the computer techs to try a different type of cable. All
 of the C-ports work when using the high speed data cable, with
 and without the USB testing tool.

 Part No Job# Description PARTS Qty Price Total

 RVDA303 1 A303 MINI BLIND WAND 1.00 3.97 3.97
 JRP81635 1 81635 2-PK POST STYLE BLIND HOLD 1.00 4.24 4.24
 FAS80-00-2040 5 Trailer Breakaway System Switch; 1.00 21.67 21.67

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00

Claim : 78937

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.26     185.00     48.10
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.24     185.00     44.40
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.20     185.00     37.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.40     185.00     74.00

```

```

Parts Total:      29.88
Labour Total:     314.50
Sublet Total:      0.00
Extras Total:      0.00

```

```

>>>> Claim Total:      344.38

```

Customer Signature: _____

Date: _____