



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78939
Promised Date:
07 FEB 26

CUSTOMER WORK ORDER

WO #: 78939

Customer: 56487 - MILLER, GREGORY -
812-483-9956

Tag:

Author: BH

Location: 0218 BH TO CLOSE

Stock #: 11557

Stock Desc: 2025 TT KEYSTONE

SPRINGDALE 261BHC

Chassis #: 4YDTSGM27S7103029

Serial #: 4YDTSGM27S7103029

Mileage:

Licence:

Invoice #:

Date In: 31 JAN 26

Promised: 07 FEB 26

Date Sched:

Completed: 19 FEB 26

Warr. Date: 07 FEB 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery. Exterior inspection looks good except the shore power outlet needs to be turned. Roof inspection looks good now i put dicor on one spot. Awning fabric and lights work properly. Interior inspection hooked up to city water and flushed out all the lines. Put water in fresh tank and ran the pump it works properly. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly. Emptied black and grey tanks and fresh tank. Did my lp drop test on outside portwith stoveand furnace running. Door side two windows had alot of budle tape hanging onarond windows. I removed it and it looks alot better. Good to go

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Used 2 gallons of winterize solution. Turned water pump valve to winterize and pumped solution through the lines to bathroom shower cold and hot until solution was there then I repeated it for bathroom faucet toilet and kitchen faucet. Then poured solution in the drains and depressed city water inlet. And drained water heater. And drained black tank and gray tanks and fresh tank.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C



Customer #: 56487
MILLER, GREGORY



Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: Hitch work

Setup hitchwork on the SUV and hookup to the trailer.

CORRECTION: Installed the hitch brackets to the camper and torqued the ball on the hitch and put the rest of the hitch in side compartment.

I setup the hitch. I found that the hitch height was not going to be low enough for the trailer. I got a longer drop bar from the parts store and installed it on the SUV. I was then able to get the right height. I hooked up to the trailer and adjusted the hitch as needed to work with the unit.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C
14-2931	90-02-4300 EQUALIZER ADJ HITCH SHANK	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #E2:				0.00

Job #BCWT - Internal

COMPLAINT: INSTALL DIGITAL, PROPORTIONAL BRAKE CONTROL IN TRUCK/SUV

CAUSE: The SUV needs a trailer brake control and wiring. It also needs a charge wire hooked up.

CORRECTION: I installed the trailer brake control and hooked up the wiring under the hood for the trailer charge wire. I tested the 7-way output and everything is working as it should.

Labor			
Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

Parts				
Part #	Description	Qty	Price	Total
14-1015	8508220 PROPORTIONAL BRAKE CONTROL	1.00	N/C	N/C
11142	TEKONSHA WIRING HARNESS - UNIVERSAL	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #BCWT:				0.00

Job #DELUXE - Internal

DELUXE STARTER KIT



W/O: 78933
Promised Date: 07 FEB 26



Customer #: 56487
MILLER, GREGORY



Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #STORAGE - Internal

COMPLAINT: STORAGE TILL MARCH 2026

CAUSE: DONE AND INSYSTEM

Other Services

Code	Description	Qty	Price	Total
STORAGE	MONTHLY STORAGE FEE	3.00	N/C	N/C

Subtotal for Job #STORAGE: 0.00

Job #1 - Warranty

COMPLAINT: SHORE CORD PLUG IN IS NOT TURNED THE RIGHT WAY

CAUSE: Shore cord receptacle turned

CORRECTION: Took shore cord receptacle off and took the back off and turn the inside about 90 degrees and put the screws back in and sealed it back up. Tested it when done and it works properly

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	54.00

Subtotal for Job #1: 54.00

Parts Total: 0.00
Labour Total: 54.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 54.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Feb 2026

