

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78954
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11696 - 2026 SPRINGDALE 2300BH 4YDTSGK27T7101267
VIN: 4YDTSGK27T7101267 HIN: SER#: 4YDTSGK27T7101267
Mileage: 0 Work Order Comp: 19 FEB 26
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 04 FEB 26 Inv #: 426609

WO # Job # Description JOB INFORMATION

78954 2 DENT IN FRIDGE DOOR
Fridge door
During pdi noticed a dent in the fridge door. Pcitrues taken
parts request submitted
78954 3 SCRATCH + DENTS IN FREEZER DOOR
Freezer door
During pdi noticed the freezer door a a piece of it taken out and
scratches on it. Pictures taken parts request submitted
78954 1 PLUG INSTALLED WRONG
Shore cord plug
During pdi noticed that the shore cord plug was upside-down. Cut
silcione around plug. Removed 4 screws holding plug in. Twisted
off back cap and other piece from outlet. Removed 3 screws
holding clear plug in. Moved plug in proper orientation. Set
screws in back of plug. Placed twist cap back into place and
screw on cap. Lined plug back into position and put screws back
in to hold on wall. Silcioned around plug.
78954 4 INSTALL BREAKAWAY IN WRONG POSITION
Breakaway switch
During pdi noticed the breakaway switch was installed inna
position underneath the lp tanks that when covered during travel
would be blocked and pinched by lp cover. Removed screw holding
switch in place and move to bottom of the aframe. Secured in

Claim : 78954

WO # Job # Description JOB INFORMATION

place. Breakaway switch is now not covered or pinched by anything
and is stand alone.

78954 5 BULGE IN BATHROOM SEAM TAPE
Buldge in seam tape.
During pdi noticed the seam tape in the bathroom was sticking
out. Felt around and two stapes were sticking out of wood seam
tape was covering. Took a mallet and taped stapes back in as
flush as they could be. Seam tape is not bulging out anymore

78954 6 SILICONE ON ROOF
Silcione on roof
During pdi noticed silcione mixed with dicor on roof.

Part No	Job#	Description	PARTS	Qty	Price	Total
672546	2	GPV10 REFRIGERATOR DOOR, BLACK		1.00	684.68	684.68
672545	3	Freezer Door - Black - Fits - GPV		1.00	380.73	380.73

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	2	MISCELLANEOUS REPAIR		0.20	180.00	36.00
Z990	2	MISCELLANEOUS REPAIR		0.30	180.00	54.00
Z990	3	MISCELLANEOUS REPAIR		0.50	180.00	90.00
Z990	3	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.20	180.00	36.00
Z990	4	MISCELLANEOUS REPAIR		0.18	180.00	32.40
Z990	4	MISCELLANEOUS REPAIR		0.02	180.00	3.60
Z990	5	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	6	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	6	MISCELLANEOUS REPAIR		0.20	180.00	36.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	2	UPS-JOBS 2,3		1.00	57.07	57.07

Parts Total: 1,065.41
Labour Total: 306.00
Sublet Total: 0.00
Extras Total: 57.07

>>>> Claim Total: 1,428.48

Customer Signature: _____

Date: _____