



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78954
Promised Date:
04 FEB 26

CUSTOMER WORK ORDER

WO #: 78954

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0220 CHECK STATUS WITH
CCV

Stock #: 11696
Stock Desc: 2026 TT KEYSTONE
SPRINGDALE 2300BH
Chassis #: 4YDTSGK27T7101267
Serial #: 4YDTSGK27T7101267
Mileage: 0
Licence:

Invoice #:
Date In: 04 FEB 26
Promised: 28 FEB 26
Date Sched:
Completed: 19 FEB 26
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00



Customer #: 1000
BASDEN'S AMERICAN RV,





Job #1 - Warranty

COMPLAINT: PLUG INSTALLED WRONG

CAUSE: Shore cord plug

CORRECTION: During pdi noticed that the shore cord plug was upside-down. Cut silicone around plug. Removed 4 screws holding plug in. Twisted off back cap and other piece from outlet. Removed 3 screws holding clear plug in. Moved plug in proper orientation. Set screws in back of plug. Placed twist cap back into place and screw on cap. Lined plug back into position and put screws back in to hold on wall. Silcioned around plug.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	36.00

Subtotal for Job #1: 36.00

Job #2 - Warranty

COMPLAINT: DENT IN FRIDGE DOOR

CAUSE: Fridge door

CORRECTION: During pdi noticed a dent in the fridge door. Pictures taken parts request submitted

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	0.00
Z990	MISCELLANEOUS REPAIR	CCV	36.00
Z990	MISCELLANEOUS REPAIR	CCV	54.00

Parts

Part #	Description	Qty	Price	Total
12673	GPV10 REFRIGERATOR DOOR, BLACK	1.00	684.68	684.68

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JOBS 2,3	1.00	57.07	57.07

Subtotal for Job #2: 831.75

Job #3 - Warranty

COMPLAINT: SCRATCH + DENTS IN FREEZER DOOR

CAUSE: Freezer door

CORRECTION: During pdi noticed the freezer door a a piece of it taken out and scratches on it. Pictures taken parts request submitted

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	90.00
Z990	MISCELLANEOUS REPAIR	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
672545	Freezer Door - Black - Fits - GPV10F	1.00	380.73	380.73

Subtotal for Job #3: 470.73

Job #4 - Warranty

COMPLAINT: INSTALL BREAKAWAY IN WRONG POSITION

CAUSE: Breakaway switch



CORRECTION: During pdi noticed the breakaway switch was installed inna position underneath the lp tanks that when covered during travel would be blocked and pinched by lp cover. Removed screw holding switch in place and move to bottom of the aframe. Secured in place. Breakaway switch is now not covered or pinched by anything and is stand alone.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	32.40
Z990	MISCELLANEOUS REPAIR	CCV	3.60

Subtotal for Job #4: 36.00

Job #5 - Warranty

COMPLAINT: BULGE IN BATHROOM SEAM TAPE

CAUSE: Buldge in seam tape.

CORRECTION: During pdi noticed the seam tape in the bathroom was sticking out. Felt around and two stapes were sticking out of wood seam tape was covering. Took a mallet and taped stapes back in as flush as they could be. Seam tape is not bulging out anymore

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	18.00

Subtotal for Job #5: 18.00

Job #6 - Warranty

COMPLAINT: SILICONE ON ROOF

CAUSE: Silcione on roof

CORRECTION: During pdi noticed silcione mixed with dicor on roof.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	CCV	36.00

Subtotal for Job #6: 36.00

Job #7 - Internal

COMPLAINT: SCRATCH ON MICROWAVE TRIM RING

CAUSE: Scratch on microwave trim ring

CORRECTION: During pdi noticed scratch on outer part of microwave trim ring. Took black paint marker to it and cover scratch.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	N/C

Subtotal for Job #7: 0.00

Parts Total: 1,065.41
Labour Total: 306.00
Sublet Total: 0.00
Extras Total: 57.07
WORK ORDER TOTAL: 1,428.48

W/O: 78954
Promised Date: 28 FEB 26



Customer #: 1000
BASDENS AMERICAN RV,



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Feb 2026

W/O: 78954
Promised Date: 28 FEB 26



Customer #: 1000
BASDENS AMERICAN RV,



Customer Work
Order

