



# KEYSTONE

## Pre-Authorization

---

Pre-Authorization number	PREAUTH704 82 (PA03962809	Reference no.	78956	Status	Approved
--------------------------	---------------------------------	---------------	-------	--------	----------

<b>Servicing Dealer</b> 1194	<b>Name</b> Basden's American RV	<b>Address</b> 600 E Baseline Rd Evansville, IN 47725	<b>VIN</b> 4YDTSGP21T7102214	<b>Retail sold on</b>
------------------------------	----------------------------------	--	------------------------------	-----------------------

For paper claims only use one pre-authorization number per warranty claim form.  
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.  
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



# KEYSTONE

Root			Approved		Actual	Base	
Operation Description	Sublet	Sub Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
2302312B Compartment Door - Lock or Latch	0	0.2	0.2		1	0.2	<b>Complaint:</b> Door side rear cargo door won't stick to magnet <b>Cause:</b> Misaligned magnets <b>Correction:</b> Opened the cargo door and took pictures of the process. Unscrewed the magnets til they lined up.
2101308B Metal Lower Wrap	0	5	3		1	0.5	<b>Complaint:</b> Dent on lower cap metal front <b>Cause:</b> Dent Took pictures of the dent on the lower cap metal. <b>Correction:</b> NEED TO REPLACE THE DAMAGED METAL
1216014B Step - Fold Up	0	0.8	0.5		1	0.5	<b>Complaint:</b> STEPS ARE BENT <b>Cause:</b> Bend in steps <b>Correction:</b> Took pictures of the damage step. NEED TO REPLACE THE DAMAGED STEP
2300102F Entrance Door - Hinged - Adjust Door or Lock	0	0.2	0.2		1	0.2	<b>Complaint:</b> ENTRY DOOR DIFFICULT TO OPEN <b>Cause:</b> Loose screws <b>Correction:</b> Opened and closed the entry door and found loose screws on the inside handle. Opened and closed the door and added dry lube.
2315002A Window - 47" or Less - Complete	0	0.2	0		1	0.5	<b>Complaint:</b> WINDOWS HAVE EXCESS PUTTY TAPE <b>Cause:</b> Putty tape <b>Correction:</b> Took pictures and used mineral spirits to clean off the extra putty tape.
Pre-Authorization number: PREAUTH70482			3.9				KRV – After careful consideration, no manufacturing defect is present.

For paper claims only use one pre-authorization number per warranty claim form.  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.  
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.