



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH748 05 (PA03966999	Reference no. 78972	Status	Approved
---------------------------------	---------------------------------	----------------------------	---------------	----------

Servicing Dealer 1194	Name Basden's American RV	Address 600 E Baseline Rd Evansville, IN 47725	VIN 4YDTCGN27TV504234	Retail sold on
------------------------------	----------------------------------	--	------------------------------	-----------------------

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root	Operation Description	Sublet	Sub Hours	Approved Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
3100803A	Cabinet Door - Repair	0	0.2	0.2		1	0.2	Complaint: SCRATCH ON CABINET SIDE OF MASTER BED Cause: There is a scratch on the panel next to the bed. Correction: Removed scratch with mineral spirits and a rag.
2300102A	Entrance Door - Hinged - Repair	0	0.2	0.2		1	0.2	Complaint: FRONT ENTRY DOOR NEEDS ADJUSTED Cause: The latch plate is hitting the door. Correction: Moved latch plate over with a hammer.
6101024B	Drain Valves with Underbelly - Handle	0	0.2	0.2		1	0.1	Complaint: HANDLE ON BLACK TANK VALVE MISSING Cause: Handle for the gate valve is missing Correction: Painted a new grey handle black. Installed handle on gate valve.
3201902A	Mirror - Repair	0	0.2	0.2		1	0.2	Complaint: GLUE ON BATHROOM MIRROR Cause: Glue on mirror. Correction: Removed glue with mineral spirits and a rag.
2300803F	Entrance Door - Hinged - Screen Door - Adjust Door	0	0.2	0.2		1	0.2	Complaint: REAR SCREEN DOOR NEEDS ADJUSTEDE Cause: The screen door is hitting the latch plate for the entry door.Moved the latch plate over with a hammer to clear the door. Correction: Moved the latch plate over with a hammer to clear the door.
6105903B	Toilet - Sealand by Dometic - Flush Lever	0	0.3	0.3		1	0.5	Complaint: THE SEAL FOR THE TOILET HOLDING WATER Cause: The toilet bowl is not holding water. Went to parts room and got a inner seal. After trying to remove the original seal,i noticed that the flapper was not in the correct location. Correction: Pull the flapper into the channel that its supposed to sit in. The toilet bowl now holds water.

Pre-Authorization number: PREAUTH74805 1.3

For paper claims only use one pre-authorization number per warranty claim form.
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.